

ASS. REG. BY:

REF:

105/ 220047081Kt

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. MCF22A00000100

Claims No. DMCF2200051H

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

LUMP SUM \$2950, 3DAYS

RED: 1787;37%

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fixes

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Cross Caster

Specimen Range
-0°20' 0°20'
-0°19' 0°20'
-0°20' 0°20'
-0°20' 0°20'

2.0

A314-32-C

10000

Gigabit Ethernet

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MCF22A00000100	Date of Loss:	07/05/2022
Vehicle Reg. No.:	SMC7322E	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Vehicle Reg. Date:	19/07/2018
Vehicle Colour:	White		
Engine No:	D4FDJH551962	Chassis No:	KNAHU815VJ7205823
Odometer:	357966 KM		

*Not Whorin
Ex \$2000*

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) *5 3 days*

Present Location: MUNICH AUTOCARE PTE LTD (HQ)

COST OF CLAIMS

Amount

Parts	2,200.00
Miscellaneous Items	85.00
Labour	1,990.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	4,275.00
- Excess (S\$)	2,000.00
(S\$)	2,275.00
+ GST 7.00% (S\$)	159.25
Nett Amount (S\$)	2,434.25

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 19 May 2022)
Parts: M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Munich Autocare Pte Ltd/SMC7322E/19/05/2022 10:19
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WIPER TANKS WITH MOTOR	0.00	0.00	RM *35.00 F ✓
2	1		*FRONT SUPPORT PANEL	0.00	0.00	B *260.00 F ✓
3	1		*FRONT ENGINE COVER	0.00	0.00	CM *95.00 F ✓
4	1		*A/COND PIPE	0.00	0.00	B *250.00 F ✓
5	1		*ENGINE OIL PAN	0.00	0.00	CM *580.00 F ✓
6	1		*FRONT CROSSMEMBER	0.00	0.00	B *780.00 F ✓

F=Franchise part.

Sub Total (S\$)	2,000.00
+ Margin on L,N Items 10.00% (S\$)	200.00
Total Parts (S\$)	2,200.00

Munich Autocare Pte Ltd/SMC7322E/19/05/2022 10:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	ENGINE OIL 5L	60.00
2	1	ENGINE UNDER COVER CLIPS	25.00
Sub Total (S\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION,BUMPER, SUPPORT PANEL,ENGINE OIL PAN AND DAMAGE AREA	New	500.00
2	TO CHECK ALL WIRING FOR OPERATION AND OIL PANT SENSOR WIRE AND PARKING SENSOR FOR OPERATION	New	120.00
3	TO REMOVE/INSTALL A/COND CONDENSOR, RADIATOR COOLING SYSTEM TO REPLACE FRONT SUPPOORT PANEL AND DAMAGE AREA	New	180.00
4	TO CONDUCT RE-PROGRAME AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	250.00
5	TO REFILL A/COND GAS	New	120.00
6	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00
7	TO REMOVE AND INSTALL FRONT CROSSMEMBER AND CONTROL SYSTEM TO FACLLITATE THE WORK	New	200.00
8	TO RESPRAY FRONT PORTION,FRONT BUMPER AND POLISH DAMAGE AREAS	New	500.00
Gross Labour Cost (S\$)			1,990.00

Munich Autocare Pte Ltd/SMC7322E/19/05/2022 10:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 May 2022)
Parts: M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Munich Autocare Pte Ltd/SMC7322E/19/05/2022 15:06
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR ASSY	0.00	0.00	<i>1 hour cna</i> *420.00 F
Sub Total (S\$)						420.00
+ Margin on L,N Items 10.00% (S\$)						42.00
Total Parts (S\$)						462.00

Munich Autocare Pte Ltd/SMC7322E/19/05/2022 15:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/05/2022 16:50 (SGT)
Date of Accident	07/05/2022 20:15 (SGT)
Exact Location of Accident	Near 11 Cavenagh Rd #02-00 Holiday Inn Singapore Orchard City Centre, Singapore 229616
Additional Location Information	CTE TOWARDS SLE/TPE AFTER CAINHILL EXIT (NEAR LAMP POST 525)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC7322E
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	+65-86881311


VEHICLE PARTICULARS

Manufacturer	Kia
Model	Carens
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1700

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	MCF22A00000100
Cover Note Number	-

DRIVER



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I was travelling along CTE towards SLE/TPE before Exit Orchard RD. I was in the middle lane, in front of me have a vehicle due to having bad vision, I cannot see clearly what is the vehicle number and model. Suddenly, vehicle B spare tyre drop direct in front of me, I cannot stopped in time so I roll over the tyre cause my undercarriage damage - That's ALL.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 10/5/22

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: