(08/11/13)	
ASS. REC. BY:	22004719 Dny
	SICAMENT
From: Date:	(0) (1) (0)
Estimated Cost:	Veh No: SKP 4231 J Yr Regn: Dec 12008
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
To Inspect Vehicle No:	
at Workshop m/s	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
of	- Indian total lilli
Insured:	0114
Policy No.	
Claims No.	C/No: J+1 MFD 4620 9 S 200 216  Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering/Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/Rim / STD A/Rim or
	Tyre Size: F: 185 60 7.15
(Policy Condition)	R: -11-
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Ten coste
Bai. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. S mm L/Bal. S mm
Est. Repairs: days Res.: Yes or No	D.O.A. 15 05 222 D.O.I. 20 05 222
Lum Sum: % 3 Val.: Yes or No	Survey held at JWG AMIC
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT  Date: Person Contacted:	RINT.
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Allianz GBL 948	
MV 141C	
LIA 4.51C NL 9.5K	
13/09/22 Juny 1/5 +,000/- with	6 das 7 las
	865.86, 85%)
Date/Time, File Pass to? : Preli. Report	ays Of Repair:
الماماء الماماء	esurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee:	: Site Insp (\$ )s+Rssi

: Interview (\$

: Tech. Invs (\$

Weekend (\$

Photos

Others

TOTAL

2)

Report Format:

Lump Sum / I.B.I: (\$

7000

SA0R225H0003 / Allswell Motor Traders ENTRY DATE & TIME: 17/05/2022 17:28 (SGT) SUBMITTED BY: Ben VERSION: 1 (17/05/2022 17:28 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission

Date of Accident

**Exact Location of Accident** 

Additional Location Information

Country/State of Loss

17/05/2022 17:28 (SGT) 15/05/2022 04:30 (SGT)

Singapore

BLK 195A RIVERVALE CRESCENT CARPARK LOT 5

Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SKP4231J

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

**Email Address** 

Mobile Phone No

Alternative Phone No

RICO ENGINEERING WORKS PTE LTD

1XXXXX407G

RAGU@RICOENG.COM.SG

(Phone) +65-64820153

+65-83382863

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

vour vehicle?

Vehicle Category Transmission

CC

Honda

Civic

Private use

No - Claiming third party

Private car

Auto

1597

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

No DMPCSNW00108312200

ThirdPartyFireTheft

China Taiping Insurance (Singapore) Pte. Ltd.

DRIVER

Name of Driver

NRIC No

Accident report SA0R225H0003

RAGU S/O SANTHIRA MANOGAR

SXXXX631A

Page 1 of 15

Date Of Birth 15/11/1984 Occupation Outdoor Date Of Driving Pass 24/10/2018 Driving experience 3 YEARS AND 7 MONTHS Gender (Phone) +65-83382863 Mobile Number Alt. Phone Number **Email Address** RAGU@RICOENG.COM.SG Address **BLK 194 RIVERVALE DRIVE** Address complement #10-775 540194 Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Employee Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Parked Vehicle Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 0 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION

CIRCUMSTANCES OF ACCIDENT

If yes, against whom?

Was the accident reported to the police?

Was notice of intended Prosecution given?

ON THE STATED DATE & TIME, I, VEHICLE A (SKP4231J) WAS PARKED AT THE STATED LOCATION. BASED ON MY VIDEO FOOTAGE, VEHICLE B (GBL94S) HAD COLLIDED ONTO MY VEHICLE WHICH CAUSED MY VEHICLE TO HIT ONTO VEHICLE C (GBG9032M).

No

No

#### ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Was there any audio recorded?

Yes

Yes

YIDEO WITH WORKSHOP

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Na / Unknown

Name of Driver

GBL94S

Vehicle Manufacturer

NA / Unknown

Name of Driver

CBL94S

NA / Unknown

NA / Unknown

NA / Unknown



Contact Number	-
Address	_
Address complement	-
Postcode	_
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBG9032M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	_
Address	-
Address complement	1.5
Postcode	-
Insurance Company Name	-
Nature Of Damage	_
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	:=:

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Poicy holder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Sketch Plan

1

Vehicle A: SKPA231J

17-May-2022

Vehicle B:

CARGE 9052 M

BIK 195A RIVERVALE Crescent Carpark Lot 5

## > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	407G
Vehicle Details	SKP4231J
Vehicle No.:	
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 May 2022
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L 5AT
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	R16A14000869
Chassis No.:	JHMFD46209S200216
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,407.00
Original Registration Date:	19 Dec 2008
First Registration Date:	19 Dec 2008
Transfer Count:	4
Actual ARF Paid:	\$20,407.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
intended COE Rebate Details	<u> 1900-lean an Airte an Airte</u>
COE Expiry Date:	(30 Nov 2023)
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$4,549.00
Total Rebate Amount:	\$4,549.00


Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 May 2022

OK

MV 14K VIN 4.5K NL 9.5K-

#### SGCARMART.COM



PREMIUM AD

# JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

To:

**ALLIANZ** 

Att:

Motor Claims Dept

ACCIDENT INVOLVING GBL94S [YOUR INSURED] & SKP4231J [OUR CLIENT] ON 15/05/2022.

## **ESTIMATED REPAIR COSTS FOR SKP4231J**

<b>QTY</b>	PARTS	<u>AMOUNT</u>	
1PC	FRONT FENDER RH/LH Devon 537.50 x 2 1075.00	\$ 1,782.00	1
1PC	FRONT FENDER INNER SHIELD RH / LH 2VZ	\$ 194.80	×
1PC	FRONT FENDER QUARTER GLASS MOULDING RH / LH HH	\$ 96.70	×
1PC	FRONT 'A' PILLAR RH	\$ 956.80	7
1PC	FRONT WHEEL HOUSING RH / LH	\$ 1,140.00	×
2. IPC	HEAD LAMP RH/LH Wollen	\$ 1,412.10	1
2 IPC	HEAD LAMP LOWER BRACKET RH / LH 15t   Deut	\$ 99.10	1
2PCS	HEADLAMP BALLAST CONTROL UNIT LH / RH	\$ 2,321.00	X
1PC	FRONT NUMBER PLATE GARNISH and 51.80	\$ 213.00	
1PC	FRONT BUMPER Dende Lton 692.40	\$ 938.00	1
2PCS	FRONT BUMPER SIDE RETAINER LH / RH 0 5 16 H 5 160	\$ 124.40	11
1PC	FRONT BUMPER REINFORCEMENT Deubl 309.50	\$ 745.00	1
1PC	FRONT BUMPER LOWER GRILLE morny crack 281.20	\$ 445.00	1
1PC	FRONT BUMPER FOG LAMP RH / LH	\$ 492.80	×
1PC	FRONT BUMPER FOG LAMP GARNISH RH / LH 0 5 HM 4/3 and should	\$ 242.80	14
1PC	FRONT BUMPER FOG LAMP HOLDER RH / LH	\$ 199.50	X8
1PC	FRONT BUMPER FOG LAMP WIRE HARNESS	\$ 980.00	×
1PC	FRONT GRILLE mondy conk 342.W	\$ 342.00	1
1PC	FRONT GRILLE OUTER CHROME CALC 199.40	\$ 3.67.00	1
1PC	FRONT GRILLE H EMBLEM ( w 43.40	\$ 113.00	-
1PC	FRONT GRILLE CLIPS Has	\$ 50.00	
1PC	FRONT WHEEL BEARING RH /LH	\$ 645.00	X
1PC	FRONT WHEEL BEARING HUB RH /LH	\$ 678.00	$\times$
1PC	FRONT ABSORBER RH / LH	\$ 1,145.00	X
1PC	FRONT LOWER ARM RH /LH HH	\$ 988.00	X
1PC	FRONT KNUCKLE ARM RH /LH HH	\$ 918.00	X
1PC	FRONT STABILIZER LINK RH / LH	\$ 395.00	$\times$
1PC	FRONT STABILIZER BAR Ly	\$ 289.40	X
1PC	FRONT TIE ROD RH / LH	\$ 337.00	X
1PC	FRONT TIE ROD END RH / LH HH	\$ 387.10	X
IPC	FRONT SUPPORT PANEL Denky UST 642.W	\$ 125000	1
	FRONT SUPPORT PANEL Dente UST 642.W		

IPC	HORN HARIVESS Sodet borner 318.30	\$ 430000
1PC	STEERING RACK & PINION ASSY HH	\$ 2,980.00 ×
1PC	DRIVE SHAFT RH / LH HA	\$ 2,481.00
1PC	FRONT DOOR RH	\$ 1,241.30 🗶
1PC	FRONT DOOR WEATHER STRIP RH	\$ 296.20 \( \lambda
1PC	FRONT DOOR CENTER MOULDING RH	\$ 296.20 🗸
1PC	FRONT DOOR WINDOW MOULDING RH	\$ 199.92 🗸
2PC	FRONT DOOR HINGE RH @ \$95.90 EACH	\$ 191.80 ×
1PC	FRONT DOOR BLACK PLASTIC MOULDING RH	\$ 146.90 ×
1PC	BONNET Devol 947.r	U \$ 947.00 L
2PC	BONNET HINGE LH / RH	\$ 223.00 ×
1PC	BONNET LOCK 154 2.39.24	\$ 323.00 ~
1PC	BONNET INSULATOR HA	\$ 221.00 🗶
1PC	BONNET INSULATOR CLIPS HA	\$ 50.00 \
1PC	SIDE SKIRT RH	\$ 789.90 /
1PC	ROCKER PANEL RH	\$ 943.10 ×
1PC	AIR RESONATOR broken 298.00	\$ 298.00
1PC	AIRCON CONDENSER SV-	\$ 1,213.00 ×
1PC	AIRCON CONDENSER SUCTION PIPE	\$ 242.00 🗶
1PC	AIRCON CONDENSER DISCHARGE PIPE	\$ 284.00 ×
1PC	AIRCON CONDENSER LIQUID PIPE HA	\$ 341.00 ×
1PC	AIRCON FAN COWLING	\$ 314.00 \( \times
1PC	AIRCON FAN BLADE	\$ 124.00 \( \times
1PC	AIRCON FAN MOTOR HA	\$ 298.00 X
1PC	RADIATOR money broken 1314.00	\$ 1,314.00
1PC	RADIATOR FAN COWLING	\$ 314.00 ×
1PC	RADIATOR FAN BLADE	\$ 124.00 🗴
1PC	RADIATOR FAN MOTOR ⊢⊷	\$ 298.00 \( \)
2PC	REAR SHOCK ABSORBER LH / RH HL	\$ 982.00 \( \times
2PC	REAR KNUCKLE ARM LH / RH	\$ 902.00 \( \times
2PC	REAR KNUCKLE ARM BEARING LH /RH	\$ 753.00 \( \square \)
2PC	REAR WHEEL BEARING HUB LH /RH المرا	\$ 783.00 \( \times
2PC	REAR LOWER ARM LH / RH	\$ 824.00 🗸
1PC	REAR AXLE 44	\$ 2,231.00 ×
1PC	WIPER WASHER TANK HA	\$ 243.00 \( \square \)
1PC	WIPER WASHER TANK MOTOR MM	\$ 315.00 ×

8618.50 6894.80 PARTS SUM: \$ 42,564.82

PARTS LESS 20%: \$ 8,512.96 PARTS TOTAL: \$ 34,051.86

## **LABOUR & SPECIAL NETT ITEMS**

*	TO SUPPLY FRONT BUMPER CLIPS -LC	\$	50.00 20
*	TO SUPPLY BONNET INSULATOR CLIPS HIM	\$	80.00 ×
*	TO SUPPLY FRONT WHEEL HOUSING SEALANT HA	\$	80.00 📈
*	TO SUPPLY 4PC TYRE	S	1 200 00 ×

* * * *	TO SUPPLY 4PC SPORT RIM HH  TO SUPPLY FRONT FENDER INNER SHIELD CLIPS HH  TO SUPPLY ROCKER PANEL SEALANT HH  TO SUPPLY SIDE SKIRT CLIPS HH  TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$ \$ \$ \$	2,400.00 50.00 80.00 50.00 400.00 HN
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	2,000.00 900  -
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00 800[-
*	TO TUFF COAT DAMAGED AREAS	\$	300.00 40 / ~
*	TO RNR FRONT UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	\$	400.00 MM
*	TO RNR REAR UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	\$	400.00 MM
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$	200.00 ⊣~
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$	120.00 ⊣⊢
	TO REMOVE AND RENEW AIRCON CONDENSER AND TOP UP GAS	\$	200.00 120 -
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00 30  -
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00

LABOUR & S/N TOTAL: \$ 10,510.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 44,561.86

20/05/2020 1700m Us 7,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

45865 - 86

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JKK And Chec