



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS/ASM22004726/Uvy3e2 Date: 01/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SQ 888R	Veh. Inspected	SCZ 1928U
	Policy No.	GA544861	Coverage (\$)	0.00
	Claim No.	S2M041EO	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	19/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF A7 (A)	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WVWZZZAUZFW073201	Colour	BLUE
	Odometer	92375 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	PIRELLI	6 mm
	L/H Front Tyre	225/40 R18	PIRELLI	6 mm
	R/H Rear Tyre	225/40 R18	PIRELLI	6 mm
	L/H Rear Tyre	225/40 R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/05/2022	Inspection Date	23/05/2022
	Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	