

ASS. REC. BY: Thuvan

REF: CS/FCI22004730/UTY3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 60k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: X2293k Yr Regn: 21/1/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Sprinter c.c 2148

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 36751 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDB9062532W77-3769

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/75R16

R: 205/75R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or duraturn

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 11/5/22 D.O.I. 19/5/22 1630

Survey held at King Auto group

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MU: 60k

rebate: 18309

Nu: 41691

estimate not ready, workshop nvr give

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_ )

☐ : Interview (\$ \_\_\_\_\_ )

☐ : Tech. Invs (\$ \_\_\_\_\_ )

☐ : Weekend (\$ \_\_\_\_\_ )

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS. \_\_\_\_ \$

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

781W

YQ293K

No

24 May 2022

MERCEDES BENZ

SPRINTER 516CDI/3665 D/CAB

White

2018

65195534790593

WDB9062532N773769

-

\$48,835.00

21 Jan 2019

21 Jan 2019

1

\$2,442.00

No

-

\$0.00

20 Jan 2029

C - Goods Vehicle & Bus

10

\$27,509.00

\$18,309.00

\$18,309.00

The information contained herein is correct as at 24 May 2022

OK

dp: 9k

12

= 750

6 yrs 8 / 80

~~8500~~ 750 x 80

= 60k

60k - 18309

= 41691