

ASS. REC. BY:

REF:

105/22004733/Kcy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

28/06/22 @ 6.47pm revised to ECICS via Merimen.

Kenneth finalised final fig \$19205.43, 7 days. (Red \$8385.50, 30%)

Date/Time, File Pass to?

1) 29/06 Typist

Date/Time, File Return to?

: Prell. Report

: Final Report

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I: (\$ 19205.43

Veh No: SMR 2P57M Yr Regn: 12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Sin Ming Autocare BFG Pte Ltd
176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 | Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

*Not Authorized
Recovery B4paim
Today*

ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600
Attn: Motor Claim Dept

ESTIMATE

VEHICLE NO: SMR2757M
MAKE/MODEL: TOYOTA CAMRY
DATE: 18.05.2022

CHASSIS: MR2B63HK304004074

No.	Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM:				
1	BOOTLID	1	1,576.90	1,576.90 ✓
2	BOOT HINGE RH	1	228.00	228.00 X
3	BOOT HINGE LH	1	228.00	228.00 X
4	BOOT LIDE HINGE COVER LH	1	85.60	85.60 X
5	BOOT LIDE HINGE COVER RH	1	85.60	85.60 X
6	BOOT LID WEATHERSTRIP	1	284.70	284.70 ✓
7	BOOT LOCK	1	423.90	423.90 X
8	BOOT OUTER MOULDING	1	245.10	245.10 X
9	BOOT EMLEM LOGO	1	85.60	85.60 ✓
10	BOOT EMBLEM 'CAMRY'	1	108.15	108.15 X
11	BOOT EMBLEM '2.5'	1	77.10	77.10 ✓
12	BOOT INNER TRIM	1	795.50	795.50 X
13	BOOT INNER TRIM CLIP	20	4.50	90.00 X
14	TAIL LAMP RH	1	914.25	914.25 ✓
15	TAIL LAMP LH	1	914.25	914.25 ✓
16	TAIL LAMP PANEL RH	1	282.70	282.70 X
17	TAIL LAMP PANEL LH	1	282.70	282.70 X
18	SPARE WHEEL PANEL	1	996.90	996.90 X
19	SPARE WHEEL PANEL COVER	1	589.80	589.80 ✓
20	REAR BODY PANEL	1	896.61	896.61 ✓
21	REAR BODY PANEL TOP GARNISH	1	334.20	334.20 ✓
22	REAR FENDER INNER TRIM LH	1	481.60	481.60 X
23	REAR FENDER INNER TRIM RH	1	481.60	481.60 X
24	REAR BUMPER	1	678.80	678.80 ✓
25	REAR BUMPER BRACKET	1	85.60	85.60 ?
26	REAR BUMPER SIDE RETAINER LH	1	131.80	131.80 X
27	REAR BUMPER SIDE RETAINER RH	1	131.80	131.80 X
28	REAR EXHAUST MUFFLER	1	1,073.80	1,073.80 X
29	REAR TAIL LAMP SIDE COVER LH	1	75.10	75.10 X
30	REAR TAIL LAMP SIDE COVER RH	1	75.10	75.10 X
31	REAR BUMPER REFLECTOR RH	1	86.50	86.50 ?
32	REAR BUMPER REFLECTOR LH	1	86.50	86.50 X
33	REAR BUMPER LOWER GARNISH	1	542.10	542.10 ✓
34	REAR BAZER SENSOR	1	198.50	198.50 ?
35	REAR REVERSE SENSOR WIRE	1	385.10	385.10 ?
36	REAR TOOL BOX	1	198.70	198.70 X
37	REAR TOOL BOX TRAY	1	215.25	215.25 ✓



Sin Ming Autocare BFG Pte Ltd
176 Sin Ming Drive
#02-05 Sin Ming Autocare
Singapore 575721
Tel : 6455 0600 / Fax : 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600
Attn: Motor Claim Dept

CHASSIS: MR2B63HK304004074

ESTIMATE

VEHICLE NO: **SMR2757M**

MAKE/MODEL: **TOYOTA CAMRY**

DATE: **18.05.2022**

38	REAR BUMPER REINFORCEMENT	1	382.20	382.20	✓
39	FRONT BUMPER	1	838.40	838.40	✓
40	FRONT BUMPER CENTER GRILLE	1	760.50	760.50	✓
41	FRONT BUMPER TOP RUBBER	1	117.15	117.15	✓
42	FRONT BUMPER CENTER GRILLE BASE	1	245.15	245.15	✓
43	FRONT GRILLE	1	450.10	450.10	✓
44	FRONT GRILLE LOGO	1	1,091.60	1,091.60	✓
45	FRONT HEADLAMP RH	1	4,635.90	4,635.90	✓
46	FRONT HEADLAMP LH	1	4,635.90	4,635.90	✓
47	FRONT SUPPORT PANEL TOP GARNISH	1	248.20	248.20	x
48	TOWING COVER	1	38.15	38.15	x

Sub Total (S\$): 27,896.66

Discount (25%): 6,974.17

Total Parts (S\$): 20,922.50

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	1	50.00	50.00	✓
2	FRONT NUMBER PLATE HOLDER	1	30.00	30.00	✓
3	REAR NUMBER PLATE	1	50.00	50.00	x
4	REAR NUMBER PLATE HOLDER	1	30.00	30.00	x
5	REAR REVERSE SENSOR CENTER RH	1	392.80	392.80	✓
6	REAR REVERSE SENSOR CENTER LH	1	392.80	392.80	✓
7	REAR CAMERA	1	480.00	480.00	x

Sub Total (S\$): 1,425.60

LABOUR:

1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT ON AFFECTED AREAS.	2,500.00	800
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON EFFECTED	1,800.00	1100
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	200.00	80
4	LABOUR TO REMOVE AND REPLACE REAR BOOTLID.	200.00	50
5	TO CHECK WIRING FUNCTIONS.	80.00	40

Total Labour (S\$):

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



for Sin Ming Autocare BFG Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	18/05/2022 11:31 (SGT)
Date of Accident	17/05/2022 17:57 (SGT)
Exact Location of Accident	SLE, Singapore
Additional Location Information	SLE TOWARDS BKE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMR2757M
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHEN YOKE KEE
NRIC No	SXXXX212F
Email Address	kirei.kirei.sg@gmail.com
Mobile Phone No	(Phone) +65-92259803
Alternative Phone No	+65-92259803

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Camry
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2487

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5124938928
Cover Note Number	-

DRIVER

Name of Driver	CHEN YOKE KEE
NRIC No	SXXXX212F

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescindulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

Sketch Plan

① SMR 2757M		SLE TO BIKE
② SMN 66366		
③ SMG 32276		
④ STL 90155		