

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: BUDGET	DATE	: 19-May-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SMG9332S		
MODEL	: TOYOTA NOAH		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 18-May-22
		TIME	: 1615HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Del</i>	1	\$ 822.30	\$ 822.30
2	REAR BUMPER SIDE RETAINER <i>Del</i>	1	\$ 62.40	\$ 62.40
3	REAR CONCAVE BUMPER LH <i>Del</i>	1	\$ 320.00	\$ 320.00
4	REAR FENDER LH <i>Not m</i>	1	\$ 1,855.30	\$ 1,855.30

1204.70
TOTAL PRICE \$ 3,060.00
LESS 25% \$ 765.00
903.52 SUB TOTAL PRICE \$ 2,295.00

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>m</i>	1	\$ 20.00	\$ 20.00
2	REFLECTOR CHROME <i>cut</i>	1	\$ 180.00	\$ 180.00

120 TOTAL \$ 200.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00	<i>200</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>500</i>	
3	TUFF COAT	\$ 250.00	<i>x</i>	

4	WIRING CHECK	\$ 120.00	X	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	

750

TOTAL \$2,450.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,495.00
TOTAL LABOUR COST : \$ 2,450.00
TOTAL REPAIR COST : \$ 4,945.00

Adnan Li
P/P 20/05/22
03 Days

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

total: 1773.52
CP/P

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: