



# SL LAW CHAMBERS

ADVOCATES & SOLICITORS, Notary Public & Commissioner For Oaths

Reg No. 53388805X

133 New Bridge Road #13 – 01 Chinatown Point, Singapore 059413

Tel : 6909 9356, Fax : 6909 6246, E-mail : prs@slaw.com.sg

Our ref : PD.192495.LH

Your ref : **SHA783Z**

Date : **28 MAR 2022**

**AXA INSURANCE PTE LTD**

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

**Attention: Motor Claims Department**

**WITHOUT PREJUDICE  
BY EMAIL**

Dear Sir,

**CLAIMANT: ZHEN CHUNMU – OWNER OF SKN2185H**

**PROPERTY DAMAGE CLAIM ARISING FROM ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES NO. SKN2185H AND SHA783Z ALONG CTE AYE BEFORE ANG MO KIO AVE 5 EXIT ON 16 JANUARY 2022 AT ABOUT 1830 HOURS**

We refer to the above matter.

We are instructed by **ZHEN CHUNMU** to claim damages against your insured in connection with a road traffic accident on **16 JANUARY 2022 ALONG CTE AYE BEFORE ANG MO KIO AVE 5 EXIT** involving **SHA783Z** driven by you / your insured's driver at the material time.

We are instructed that the accident was caused by your / your insured driver's negligence. As a result of the accident, our client suffered damages, loss and expenses of which particulars are set out in the report(s) annexed hereto this letter:

a)	Cost of Repair (Incl. of GST)	: S\$ 12,529.70
b)	Loss of Rental (\$180.00/day x 10 days)	: S\$ 1,800.00
c)	Survey Report Fee	: S\$ 684.00
d)	LTA / GIA search fee	: S\$ 43.94
e)	Coloured Photographs (\$1.00 x 24 pages)	: S\$ 24.00
f)	Incidentals	: S\$ 150.00
g)	Costs	: S\$ 1,605.00
<b>Total</b>		<b>: S\$ 16,836.64</b>

A copy each of the following supporting documents is enclosed:

- (1) Our client's GIA/TP report;
- (2) LTA Search;
- (3) Vehicle Rental Invoice / Receipt;
- (4) Final Repair Bill; and
- (5) Survey Report with Photographs

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurers.



# S L LAW CHAMBERS

ADVOCATES & SOLICITORS, Notary Public & Commissioner For Oaths

Reg No. 53388805X

**133 New Bridge Road #13 – 01 Chinatown Point, Singapore 059413**

**Tel : 6909 9356, Fax : 6909 6246, E-mail : [prs@slaw.com.sg](mailto:prs@slaw.com.sg)**

=====

Please note that you or your insurer should send to us an acknowledgement of receipt to us within 14 days of your receipt of this letter. Should you/your insurer fail to acknowledge receipt of this letter within 14 days, our client may commence Court proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

**S L LAW CHAMBERS**

Encl

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	17/01/2022 15:00 (SGT)
Date of Accident	16/01/2022 18:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE AYE before Ang Mo Kio Ave 5 Exit
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN2185H
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ZHENG CHUNMU
Passport No/FIN	G0791511Q
Email Address	WENGHAI99@GMAIL.COM
Mobile Phone No	(Phone) +65-93862606
Alternative Phone No	+65-93862606

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	X3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5096901722-04
Cover Note Number	-

### DRIVER

Name of Driver	ZHENG CHUNMU
Passport No/FIN	G0791511Q



Date Of Birth	25/08/1967
Occupation	Indoor
Date Of Driving Pass	23/09/2010
Driving experience	11 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93862606
Alt. Phone Number	+65-93862606
Email Address	WENGHAI99@GMAIL.COM
Address	51 EDEN GROVE
Address complement	-
Postcode	539093 V
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	Passenger
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Serangoon Neighbourhood Police Centre
Police Station Address	50 Serangoon Avenue 2 #01-02
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN / POLICE REPORT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA783Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-



Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	NG KAR SNEG
NRIC No	S1214595J
Contact Number	(Phone) +65-96588281
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLG7295R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	ZHENG CHUNMU
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKN2185H
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

##### INJURED 2

Name of injured person	DRIVER
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLG7295R
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	Yes

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 17/01/2022 14:43

Report No: MT

D.O.A: 16/01/2022  
Time: 18:30 hrs

Vehicle No: SKN2185H

Reporting Type:

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




17/01/22 14:43  
Policyholder's Signature / Date & Time


17/01/22 14:43

Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

  
Witnessed by Reporting Centre Personnel

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Declaration

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

17/01/22 / 14:43

Policyholder's Signature / Date & Time

17/01/22 / 14:43

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

*[Signature]*

Witnessed by Reporting Centre Personnel

































**SINGAPORE  
POLICE FORCE**



T/20220116/2062

Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

1 of 3

Report No: T/20220116/2062

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 16/01/2022 21:03	Vide Report No.: F/20220116/0200	Station Diary No.: 43
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: ZHENG CHUNMU	Address: 51 EDEN GROVE SINGAPORE 539093		
ID Type / ID No.: FIN NO / G0791511Q	Contact No.: Home/Office: Mobile: 93862606		
Nationality: CHINESE	Email:		
Sex Male	Age: 54	Date of Birth: 25/08/1967	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: MANAGING DIRECTOR	Driving Licence Information: Class: 2B,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 16/01/2022 18:30	Type of Location: Straight Road
Location:  CENTRAL EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA783Z	Car					1
SKN2185H	Car	BMW	X3 XDRIVE20i ABS 4WD HID DSC	Silver		1
SLG7295R	Car					0



**SINGAPORE  
POLICE FORCE**



T/20220116/2062

Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

2 of 3

Report No. T/20220116/2062

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SKN2185H	NTUC Income Insurance Co-Operative Limited	5096901722-04	26/12/2021	25/12/2022

**Brief Details.**

On 16/1/22 at about 1832hrs, I was driving my car SKN2185H along CTE towards AYE and at that point of time I was at the 1st lane from the right. During that point of time my lane was clear and I saw one yellow taxi SHA783Z, wanting to switch lane to my lane without signaling. I quickly slowed down for him to switch to my lane. The head of the taxi was already in the 1st lane, however, one black car SLG7295R suddenly hit onto the taxi from the back, and as a result the taxi driver's door hit onto the front left portion of my car. After the hit, the taxi continued to drive to the 1st lane.

All of us stopped the vehicle and came out of the car. I asked the taxi driver why he shifted his car and he explained that he could not brake on time. The black car driver came out and was seen in pain and ambulance was called. Traffic Police and ambulance came thereafter and the black car driver was conveyed by the ambulance. We also took photos of the accident and exchange particulars and the traffic police advised us to make an accident report.

I am also making this report for insurance claim.





**SINGAPORE  
POLICE FORCE**



T/20220116/2062

3 of 3

Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

Report No. T/20220116/2062

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report

F/

Other YUANA BINTE KASSIM

Sgt 3 Leo Jing Xun

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/01/2022 21:03

Officer In Charge Of Case:

TP / GIT /

Sgt 3 MUHAMMAD SYARIFUDDIN

MUHAMMAD AJMAIN

Contact No: 65476367

Classification Of Case



Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

1 of 3

Report No. T/20220116/2062

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 16/01/2022 21:03		Vide Report No.: F/20220116/0200		Station Diary No.: 43	
<b>Informant's Particulars</b>					
Name of Informant: ZHENG CHUNMU			Address: 51 EDEN GROVE SINGAPORE 539093		
ID Type / ID No.: FIN NO / G0791511Q			Contact No.: Home/Office: Mobile: 93862606		
Nationality: CHINESE			Email:		
Sex: Male	Age: 54	Date of Birth: 25/08/1967	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: MANAGING DIRECTOR			Driving Licence Information: Class: 2B,3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 16/01/2022 18:30	Type of Location: Straight Road
Location:  CENTRAL EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA783Z	Car					1
SKN2185H	Car	BMW	X3 XDRIVE20I ABS 4WD HID DSC	Silver		1
SLG7295R	Car					0



**SINGAPORE  
POLICE FORCE**



T/20220116/2062

3 of 3

Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

Report No. T/20220116/2062

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report  
F /  
Other YUANA BINTE KASSIM  
SA 3 Teo Jing Xun

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
16/01/2022 21:03

Officer In Charge Of Case:  
TP / GIT /  
Sgt 3 MUHAMMAD SYARIFUDDIN  
MUHAMMAD AJMAIN  
Contact No.: 65476367

Classification Of Case:





Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 18 Jan 2022 / 13:38:58

Receipt Date/Time : 18 Jan 2022 / 13:38:58

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-220118-001882

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHA783Z				
As at 16 Jan 2022/18:30:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SHA783Z Enquiry Fee 20220118133751921960	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
<b>Total Before Rounding</b>		7.00	0.49	7.49
<b>Rounding Difference</b>				0.04
<b>Total Amount Payable</b>				7.45
Paid By				
426588XXXXXX3454		eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



# INVOICE

LCH CAR SERVICES (PTE LTD)  
Singapore

Mobile: 86853446

BILL TO  
**Gold Autoworks**

claims@goldautoworks.com.sg

Invoice Number: 298

Invoice Date: January 27, 2022

Payment Due: January 27, 2022

Amount Due (SGD): \$1,800.00

Items	Quantity	Price	Amount
<b>Car Rental</b> Car Model: BMW 523i Car Plate: SLM5635A Rental Period: 18/01 - 27/01 (inclusive)	10	\$180.00	\$1,800.00
<b>Total:</b>			\$1,800.00
<b>Amount Due (SGD):</b>			<b>\$1,800.00</b>

## Notes / Terms

LCH CAR RENTAL (PTE LTD)

Reg No: 201601642C

Address: Blk 524 Hougang Ave 6 #06-139 S530524

Hirer: ZHENG CHUNMU



# GOLD AUTOWORKS

48 Toh Guan Rd East, Enterprise Hub

#01-119, Singapore 608586

Email : claims@goldautoworks.com.sg

Fax : 6264 5948

Company Registration : 201716329M

GST Registration No : 201716329M

## Tax Invoice : GA-21-SKN2185H

Customer Name : MR ZHENG CHUNMU  
Vehicle No : SKN2185H  
Make : BMW  
Model : X3 Xdrive20i  
Chassis number : WBAWX320900B28693

Accident Date : 16/Jan/22  
Contact No : 98719488  
Mileage : 173931KM  
Attended By : WINSTON CHUA  
Delivery Date : 27/1/2022

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1	SKN2185H LUMP SUM REPAIR	1		\$11,710

SINGAPORE DOLLARS

- 1) GOODS SOLD ARE NOT RETURNABLE.
- 2) ALL CHEQUE TO BE CROSSED AND DRAWN IN FAVOUR  
OF GOLD AUTO WORKS PTE LTD

GRAND TOTAL \$ 11,710.00  
GST \$ 819.70  
NETT TOTAL \$ 12,529.70

FOR & ON BEHALF OF  
GOLD AUTO WORKS PTE LTD

AUTHORISED SIGNATURE AND COMPANY  
STAMP

LESS DISCOUNT

TOTAL PAYMENT

BALANCE \$ 12,529.70





# PROMINENT APPRAISER SERVICES PTE LTD

**Qualified Loss Adjusters And Motor Appraisers**

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## INVOICE

To. Mr Zheng Chunmu  
C/o. 48 Toh Guan Road East  
#01-119 Enterprise Hub  
Singapore 608586

Invoice No. : HA/2202-08

Date : 08/02/2022

Descriptions	Amount (SGD)
<b>Services rendered for appraiser / inspection report :-</b>	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
<b>Total :</b>	<b>SGD : \$ 684.00</b>
SGD Dollar : Six Hundred Eighty Four Dollars Only.	
Our Reference : PAS/TP/0250122	
Vehicle No. : SKN2185H	
Make & Model : BMW X3 Xdrive20I	
Your Claim No. : Third Party Claim	

### Notes:

All cheque payment should be Crossed and made payable to "**PROMINENT APPRAISER SERVICES PTE LTD**".

Please indicate our "**INVOICE NO.**" on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For **PROMINENT APPRAISER SERVICES PTE LTD**



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0250122

Date of Report : 08/02/2022

To : Mr Zheng Chunmu  
C/o. 48 Toh Guan Road East  
#01-119 Enterprise Hub  
Singapore 608586

Date of Assignment : 19/01/2022  
Report requested by : Mr Zheng Chunmu  
Date of Accident : 16/01/2022  
Date of Inspection : 19/01/2022  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SKN2185H  
Make & Model : BMW X3 Xdrive20I  
Date of Registration : 23/05/2014  
Colour : Met. Beige

Engine Capacity (cc) : 1997cc  
Mileage (km) : 173931km  
Chassis / Frame No. : WBAWX320900B28693  
Engine No. : A6620646N20B20A

### TYRE CONDITION

Front LH : 6 mm  
Make : Pirelli

Front RH : 6 mm  
Make : Pirelli

Rear LH : 6 mm  
Make : Pirelli

Rear RH : 6 mm  
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Gold Autoworks Pte Ltd  
48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586

### ASSESSMENT

Repairer's Estimate : \$ 17,666.16  
Revised Amount : \$ 14,634.20  
Less Excess : \$ -  
Recommended Reserve : \$ 11,710.00 (Lump Sum)

Estimated Normal Period of Repairs : 7 Working Days

**Disclaimer:** The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.





# PROMINENT APPRAISER SERVICES PTE LTD

**Qualified Loss Adjusters And Motor Appraisers**

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SKN2185H

Report No. : PAS/TP/0250122

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd, 48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the LHF portion. (The LHF roadwheel was also affected)

### DAMAGES

The bonnet, front bumper, LH headlamp, LHF fog lamp, LHF fender, LHF apron panel assy, front carrier air duct, LHF headlamp support, LHF alloy rim, LHF knuckle arm, LHF shock absorber, LHF strut bar, LHF wishbone, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$14,634.20.

### CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$11,710.00.

This inspection was conducted entirely on a '**Without Prejudice**' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

**Prominent Appraiser Services Pte Ltd**

  
**Andrew How**  
**Automobile Appraiser**  
**MSAAA**  
**Licensed Appraiser**



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SKN2185H

Report No. : PAS/TP/0250122

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Bonnet	Dented/Distorted	\$ 1,844.20	\$ 1,844.20
2	1 pc	Bonnet emblem (Logo)	Necessary	\$ 75.10	\$ 75.10
3	1 pc	Headlamp (Bi-xenon) LH	Cracked/Broken	\$ 2,606.50	\$ 2,606.50
4	1 pc	Frt bumper	Dented	\$ 1,314.20	\$ 1,314.20
5	1 pc	Frt bumper fog lamp LH	Loop Broken	\$ 281.60	\$ 281.60
6	2 pcs	Frt bumper PDC sensor LH	Damaged	\$ 511.60	\$ 255.80
7	1 pc	Frt bumper lower trim	Cracked/Deformed	\$ 274.30	\$ 274.30
8	1 pc	Frt bumper bracket LH	Dented/Cracked	\$ 95.90	\$ 95.90
9	1 pc	Frt bumper grille LH	Cracked	\$ 88.70	\$ 88.70
10	1 pc	Frt bumper absorber	Dented/Broken	\$ 62.60	\$ 62.60
11	1 pc	Frt bumper reinforcement	Dented/Bent	\$ 517.30	\$ 517.30
12	1 pc	Frt bumper reinforce bracket LH	Dented/Bent	\$ 146.70	\$ 146.70
13	1 pc	Frt carrier air duct	Dented/broken	\$ 333.60	\$ 333.60
14	1 pc	Frt headlamp support LH	Dented/Cracked	\$ 194.60	\$ 194.60
15	1 pc	Frt apron panel assy LH	Dented/Repair	\$ 1,631.90	\$ -
16	1 pc	Frt fender LH	Dented/Distorted	\$ 847.60	\$ 847.60
17	1 pc	Frt fender signal lamp LH	Refit	\$ 42.90	\$ -
18	1 pc	Frt fender arch protector LH	Dented/Cracked	\$ 198.30	\$ 198.30
19	1 pc	Frt fender bracket LH	Dented/Bent	\$ 57.80	\$ 57.80
20	1 pc	Frt fender cowl LH	Torn/Deformed	\$ 143.50	\$ 143.50
21	1 pc	Frt alloy rim (V Spoke 307) LH	Dented/Defaced	\$ 1,018.30	\$ 1,018.30
22	1 pc	Frt wheel hub LH	Warped/Damaged	\$ 543.20	\$ 543.20
23	1 pc	Frt knuckle arm LH	Bent/Distorted	\$ 573.80	\$ 573.80
24	1 pc	Frt ABS sensor LH	Damaged	\$ 229.80	\$ 229.80
25	1 pc	Frt shock absorber LH	Bent/Jammed	\$ 680.30	\$ 680.30
26	1 pc	Frt strut bar LH	Bent	\$ 269.10	\$ 269.10
27	1 pc	Frt wishbone LH	Bent	\$ 283.20	\$ 283.20
28	1 pc	Frt stabilizer bar	Refit	\$ 405.40	\$ -
29	1 pc	Frt stabilizer link LH	Refit	\$ 102.90	\$ -
30	1 pc	Frt apron panel assy LH	Dented/Repair	(Refer labour no. 5 & 6)	
				\$ 15,374.90	\$ 12,936.00
Less Discount : 5%				\$ 768.75	\$ 646.80
List Parts Sub-Total :				\$ 14,606.16	\$ 12,289.20
1	1 pc	Frt tyre LH (Depreciate 10%)	Cut	\$ 350.00	\$ 315.00
2	1 bot	Brake fluid	Necessary	\$ 20.00	\$ 20.00
Special Nett Sub-Total :				\$ 370.00	\$ 335.00
Parts Total :				\$ 14,976.16	\$ 12,624.20





# PROMINENT APPRAISER SERVICES PTE LTD

**Qualified Loss Adjusters And Motor Appraisers**

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SKN2185H

Report No. : PAS/TP/0250122

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall electrical wiring system for necessary repairs. To check electrical system and calibrate/focus headlamp.	\$ 60.00	\$ 50.00
2	To remove, check and replace LHF undercarriage parts. (Include flush and bleed brakes system)	\$ 250.00	\$ 220.00
3	To conduct wheel alignment.	\$ 60.00	\$ 60.00
4	To remove, replace and/or transfer front PDC sensors to new bumper. (Include reset/reprogram control unit)	\$ 120.00	\$ 120.00
5	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 660.00
6	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	\$ 900.00
Labour Total :		<u>\$ 2,690.00</u>	<u>\$ 2,010.00</u>
Total (Parts & Labour) :		<u>\$ 17,666.16</u>	<u>\$ 14,634.20</u>

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 11,710.00


Under normal circumstances, the repairs should be completed within a reasonable period

of **7 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

94 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.
































































SPS



SPS




SPS



SPS










PS  
43



PS  
43



PS  
43



PS  
43













