

Your Ref: III.21.0065-WT/rs

Date: 16th Jun 2022

Our Ref: CS1/LAW22004740/Utce2

M/s India International Insurance PL

64 Cecil Street

#05-02 IOB Building

Singapore 049711

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGC 4844G

INSURED VEHICLE: SG 1235X

ACCIDENT DATE: 16/03/2019

We thank you for your instruction on 13/05/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGC 4844G from M/s KM Auto Assessors Pte. Ltd.
- b) Survey report by Autoprobe Consultants with colour photographs.
- c) Final Repair Bill of SGC 4844G from M/s Choon Hock Autocare Pte Ltd.
- d) Singapore Accident Statement of Vehicles SGC 4844G and SG 1235X.
- e) Police Report of Vehicles SGC 4844G.
- f) Colour damaged vehicle photographs of SGC 4844G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGC 4844G
Make & Model	: Toyota Lexus GS300
Chassis Number	: JTHBG96S005022633
Year of Registration	: 2006
Engine Capacity	: 2994 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.