

AUTOPROBE CONSULTANTS

To: SBS TRANSIT LTD
205 BRADDELL ROAD
SINGAPORE 579701

Our Ref.: SVY190300152
Date: 13/06/2019

AUTOMOBILE INSPECTION REPORT

1. SURVEY TYPE: THIRD PARTY

Vehicle Inspected:	SGC-4844-G	Your Reference:	IP201901848/PJ
Insured Vehicle:	SG -1235-X	Policy Excess:	-
Assigned by:	MISS SALEHA	Assignment Date:	19/03/2019
Date of Accident:	16/03/2019	Surveyed / Assessed Date:	19/03/2019
Repairer / Survey at:	CHOON HOCK AUTOCARE PTE LTD	Resurvey Date:	20/03/2019, 26/03/2019

2. VEHICLE PARTICULARS:

Make & Model:	TOYOTA LEXUS GS300	General Condition:	FAIR
Registration Date:	18/01/2006	Colour:	BLACK
Engine Capacity:	2995	Odometer (km):	126154
Chassis No.:	JTHBG96S005022633	Steering:	IN ORDER
Engine No.:	3GR0129870	Brake:	IN ORDER

3. TYRE CONDITION:

	Size	Make	Thread Depth (%)
FRONT LEFT	225/50R17	PIRELLI	50
FRONT RIGHT	225/50R17	PIRELLI	50
REAR LEFT	225/50R17	BRIDGESTONE	50
REAR RIGHT	225/50R17	BRIDGESTONE	50

4. DESCRIPTION OF DAMAGES:

The vehicle sustained damages mainly at the rear portion.

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 2 of 140



Photograph 1 of 140



Photograph 4 of 140



Photograph 3 of 140


AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 6 of 140



Photograph 5 of 140



Photograph 8 of 140



Photograph 7 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 10 of 140



Photograph 9 of 140



Photograph 12 of 140



Photograph 11 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019




Photograph 14 of 140



Photograph 13 of 140



Photograph 16 of 140



Photograph 15 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 18 of 140




Photograph 17 of 140



Photograph 20 of 140



Photograph 19 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019




Photograph 22 of 140



Photograph 21 of 140



Photograph 24 of 140



Photograph 23 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019




Photograph 26 of 140



Photograph 25 of 140



Photograph 28 of 140



Photograph 27 of 140

AUTOPROBE CONSULTANTS


Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 30 of 140



Photograph 29 of 140



Photograph 32 of 140



Photograph 31 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 34 of 140



Photograph 33 of 140



Photograph 36 of 140



Photograph 35 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 38 of 140




Photograph 37 of 140



Photograph 40 of 140



Photograph 39 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 42 of 140



Photograph 41 of 140



Photograph 44 of 140



Photograph 43 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 46 of 140



Photograph 45 of 140



Photograph 48 of 140



Photograph 47 of 140




AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 50 of 140



Photograph 49 of 140



Photograph 52 of 140



Photograph 51 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152


Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 54 of 140



Photograph 53 of 140



Photograph 56 of 140



Photograph 55 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 58 of 140



Photograph 57 of 140



Photograph 60 of 140



Photograph 59 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 62 of 140



Photograph 61 of 140



Photograph 64 of 140




Photograph 63 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019


Photograph 66 of 140



Photograph 65 of 140



Photograph 68 of 140



Photograph 67 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 70 of 140



Photograph 69 of 140



Photograph 72 of 140



Photograph 71 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 74 of 140




Photograph 73 of 140



Photograph 76 of 140



Photograph 75 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 78 of 140



Photograph 77 of 140



Photograph 80 of 140



Photograph 79 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019




Photograph 82 of 140



Photograph 81 of 140



Photograph 84 of 140



Photograph 83 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019




Photograph 86 of 140



Photograph 85 of 140



Photograph 88 of 140




Photograph 87 of 140

AUTOPROBE CONSULTANTS


Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 90 of 140




Photograph 89 of 140



Photograph 92 of 140



Photograph 91 of 140




AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152


Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019




Photograph 94 of 140



Photograph 93 of 140



Photograph 96 of 140



Photograph 95 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 98 of 140




Photograph 97 of 140



Photograph 100 of 140



Photograph 99 of 140



AUTOPROBE CONSULTANTS


Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 102 of 140




Photograph 101 of 140



Photograph 104 of 140



Photograph 103 of 140




AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019




Photograph 106 of 140



Photograph 105 of 140



Photograph 108 of 140



Photograph 107 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019



Photograph 110 of 140



Photograph 109 of 140



Photograph 112 of 140



Photograph 111 of 140

AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 114 of 140



Photograph 113 of 140



Photograph 116 of 140



Photograph 115 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 118 of 140



Photograph 117 of 140



Photograph 120 of 140



Photograph 119 of 140



AUTOPROBE CONSULTANTS


Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 122 of 140



Photograph 121 of 140



Photograph 124 of 140



Photograph 123 of 140




AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 126 of 140



Photograph 125 of 140



Photograph 128 of 140



Photograph 127 of 140



AUTOPROBE CONSULTANTS

Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 130 of 140




Photograph 129 of 140



Photograph 132 of 140



Photograph 131 of 140



AUTOPROBE CONSULTANTS


Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 134 of 140



Photograph 133 of 140



Photograph 136 of 140



Photograph 135 of 140



AUTOPROBE CONSULTANTS


Your Ref.: IP201901848/PJ
Our Ref.: SVY190300152

Vehicle No.: SGC-4844-G
Date of Accident: 16/03/2019

Photograph 138 of 140



Photograph 137 of 140



Photograph 140 of 140



Photograph 139 of 140

