

(08/11/19)

ASS. REC. BY:

Thuan

REF:

Ching

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHA4372A

Yr Regn:

27/12/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota prius

c.c 1798

Colour

blue

A/C: Insured / Std / NI / NA

Sp. Reading

196270

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

STD183FUX03090562

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/4/22

D.O.I.

25/4/22 1730

Survey held at

CDGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA provided

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

China (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 25.04.2022
Time: 09:38:27 Juman
Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755JOB NO : 305513539
REGN NO : SHA4372A
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 27.12.2019
DATE/TIME IN : 23.04.2022 10:35
ACCIDENT DATE : 22.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-1150-A	BUMPER PROTECTOR MAT	1	N	50.00	0.00	50.00	XSV
0002	04-01-0302-2267-G	BUMPER PIECE	10		22.00	25.00	16.50	/NIC
0003	04-01-0302-2282-G	COVER REAR BUMPER	1		503.04	25.00	377.28	XV
0004	04-01-0302-3937-G	RETAINER RR BUMPER SIDE R	1		94.80	25.00	71.10	/NIC
0005	03-01-0302-2020-G	WHEEL DISC	1		1,555.00	25.00	1,166.25	/Scr
0006	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	N	80.00	2.50	80.00	/NIC

SUB-TOTAL : 1,761.13

JOB NATURE

0000	PB	PANEL BEATING			800.00	700
0001	SP	SPRAYPAINT CHARGE			800.00	24 750
0002	L	REMOVE/REFIX REVERSE SENSOR			50.00	30

SUB-TOTAL : 1,650.00

Thru
82235769
25/4/22 1730
P/P 3day swp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

Date/Time: 25.04.2022 09:02

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO: 305513539

Customer

Customer Name: COMFORT TRANSPORTATION PTE LTD

Customer No: 7010045

Address: 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(D)

(P)

Print Card No

REGISTRATION	SHA4372A	MILEAGE
MAKE	TOYOTA	FUEL
MODEL	PRIUS HYBRID(G4A23	DATE/TIME IN
YR OF MANU	27.12.2019	TARGET DATE
CHASSIS CODE	JTDKBB3FUX03090562	COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 22.04.2022

Accident Time: 3P 22.04.2022

/NO

LABOR CODE

DESCRIPTION



Worked & Passed Out By:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Work Order Slip

Exit Pass

Vehicle No.: SHA4372A

JU CHINA

Vehicle No.:

SHA4372A

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard