

(08/11/19)

ASS. REC. BY: thuanREF: ching**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHH4372A Yr Regn: 27/12/19Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Togofa prius c.c 1798Colour: blue A/C: Insured / Std / NI / NASp. Reading: 196270 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDH83FUX03090562Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 22/4/22 D.O.I. 25/4/22 1730Survey held at CDGEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NO GIA provided

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report
1) _____
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

China (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 25.04.2022

Jumani

REPAIR ESTIMATE

Time: 09:38:27

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305513539
 REGN NO : SHA4372A
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4A)
 DATE OF REGN : 27.12.2019
 DATE/TIME IN : 23.04.2022 10:35
 ACCIDENT DATE : 22.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-1150-A	BUMPER PROTECTOR MAT	1	N	50.00	0.00	50.00	XSV
0002	04-01-0302-2267-G	BUMPER PIECE	10		22.00	25.00	16.50	/NIC
0003	04-01-0302-2282-G	COVER REAR BUMPER	1		503.04	25.00	377.28	XV
0004	04-01-0302-3937-G	RETAINER RR BUMPER SIDE R	1		94.80	25.00	71.10	/NIC
0005	03-01-0302-2020-G	WHEEL DISC	1		1,555.00	25.00	1,166.25	/Scr
0006	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	N	80.00	2.50-	80.00	/NIC

SUB-TOTAL : 1,761.13

JOB NATURE

0000	PB	PANEL BEATING	800.00	700
0001	SP	SPRAYPAINT CHARGE	800.00	74 756
0002	L	REMOVE/REFIX REVERSE SENSOR	50.00	30

SUB-TOTAL : 1,650.00

Thavin
 82235769
 25/4/22 1730
 P/P 3dayswp

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: