

Date : 23.05.2022

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

To **LKK**

Fax:

Attn : **GUO QIANG**

Vehicle Reg No. : **SHA2607L**

18.05.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: **CHINA** **SLP5973X**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

\$800.00

Total for Part-By-Part Repair Cost

\$800.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Signature: _____

Name : CHIANG

Name :

Tel : 62148314

Date _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks: