

AXIA (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.05.2022

REPAIR ESTIMATE

Time: 08:48:10

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305516805
REGN NO : SHA8079X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 04.08.2020
DATE/TIME IN : 21.05.2022 08:15
ACCIDENT DATE : 20.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT			
0001	04-01-0302-2282-G	COVER REAR BUMPER	1	503.04	25.00	377.28	de ✓
0002	04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50	na ✓
0003	04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1	654.96	25.00	491.22	de ✓
0004	04-01-0302-2346-G	GARNISH S.ASSY BACK DOOR	1	1,054.71	25.00	791.03	Rx ma ✓
0005	28-01-0302-0006-A	REAR BOOT 65521111 CTPL	1 N	30.00	2.50-	30.00	na ✓
0006	28-01-0302-2013-A	REAR BONNET APP TAXI BOOK	1 N	40.00	0.25	40.00	na ✓
0007	04-01-0302-2270-G	PLATE-BACK DOOR NAME (HYB	1	62.14	25.00	46.60	na ✓
0008	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	2.50-	30.00	na ✓
0009	04-01-0302-2271-G	PLATE-BACK DOOR NAME (PRI	1	62.14	25.00	46.60	na ✓

2358.99
1769.24
SN 100

SUB-TOTAL : 1,869.23

JOB NATURE

0000 PB	PANEL BEATING	800.00	350
0001 SP	SPRAYPAINT CHARGE	600.00	500

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305516805
 REGN NO : SHA8079X
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID
 DATE OF REGN : 04.08.2020
 DATE/TIME IN : 21.05.2022 08:1
 ACCIDENT DATE : 20.05.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30	
0003 20-05	ADVERTISMENT STICKER-BUMPER	50.00	24	
0004 20-05	ADVERTISMENT STICKER-FENDER	200.00	24	1130
		SUB-TOTAL : 1,700.00		

TOTAL : 3,569.23

Juman!

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Teuphu 97695749
23/5/22 @ 5pm
2 days
p/b Resurvey before paint
Sanjiv Kulkarni. car

1769.24
100
1130
2999.24
2692400
2 days #

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: