

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM22004832/Tga3q2	
	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date:	20/07/2022	
	ATTN:CYNTHIA		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7815U	Veh. Inspected	SHC 6903U	
	Policy No.	P2465679	Coverage (\$)	0.00	
	Claim No.	S2M041TN	Excess (\$)	0.00	
	Assign From		Assign Date	23/05/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	KIA OPTIMA	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KNAGM414MF5593872	Colour	SILVER	
	Odometer	767430 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/65 R15	HANKOOK	6 mm	
	L/H Front Tyre	205/65 R15	HANKOOK	6 mm	
	R/H Rear Tyre	205/65 R15	HANKOOK	6 mm	
	L/H Rear Tyre	205/65 R15	HANKOOK	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/05/2022	Inspection Date	23/05/2022	
	Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD				
	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				