

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 23/05/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMY1587G		
MODEL	: TOYOTA SIENTA 1.5A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 21-May-22
		TIME	: 14:10HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehanded</i>	1	\$ 620.50	\$ 620.50
2	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.40	\$ 124.80
3	FRONT BUMPER SPONGE <i>new</i>	1	\$ 123.60	\$ 123.60
4	CENTRE GRILLE ASSY <i>new</i>	1	\$ 688.50	\$ 688.50
5	CENTRE GRILLE CHROME RH <i>new</i>	1	\$ 180.20	\$ 180.20
6	CENTRE GRILLE LOGO <i>new</i>	1	\$ 90.00	\$ 90.00
7	HEADLAMP RH <i>new</i>	1	\$ 1,155.20	\$ 1,155.20

TOTAL PRICE \$ 2,982.80
LESS 25% \$ 745.70

SUB TOTAL PRICE \$ 2,237.10

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ 20.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>200</i>	
---	--	-------------	------------	--

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	200	
3	TUFF COAT	\$ 150.00	X	
4	WIRING CHECK	\$ 80.00	30	

TOTAL

\$2,230.00

430

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,257.10
TOTAL LABOUR COST : \$ 2,230.00
TOTAL REPAIR COST : \$ 4,487.10

APPROVED DETAILS

SURVEYOR :
CONTACT NO :
PART BY PART / LUMP SUM :
NO OF DAYS :

FAX

Adrian L
H/S 24/05/22

03 Days.

total: 2524.12

H/S: 21c

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: