

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIANZ INSURAN	NCE SINGAPORE PTE LTD	Ref	f: CS/AIS22004839/Vqy3m4	
	79 ROBINSON RO #09-01 SINGAPOR		Dat	te: 01/08/2022	
			Co	de: AIS	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 1307Z	Veh. Inspected	SMJ 2665L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	2022 22004889SL	Excess (\$)	0.00	
	Assign From	SHANTI	Assign Date	23/05/2022	
2.	. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO 1.6 SX	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	KNAF3416MK5024856	Colour	SILVER	
	Odometer	34815 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/05/2022	Inspection Date	24/05/2022	
	Survey held at	CYCLE & CARRIAGE.FULCO M	OTOR DEALER PL		
		NO.330 UBI ROAD 3 SINGAPORE 408650			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			