

ASS. REC. BY: THEVANREF: CS/AIS 72064834/VAY3**ASSIGNMENT**From: _____ Date: _____
Estimated Cost: _____OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 2022 22004889SL

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 85k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMJ266SL Yr Regn: 27/2/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HiA Cerato 1.6 SX c.c. 1591Colour Silver A/C: Insured / Std / NI / NASp. Reading 34815 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNJFF3416MK5024856Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R14R: 225/45R14BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm L/Bal. 6 mmL/Bal. 6 mm D.O.I. 24/5/22D.O.A. 17/5/22Survey held at Cycle and CarriageDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 85kRebate: 30466NV: 54534

Thevan finalised final fig \$2956, 4 days. (Red \$3081, 51%)

Date/Time, File Pass to?

1) 01/08 Typist

Date/Time, File Return to?

2)

Report Format : TPLump Sum / I.B.I: (\$ 2956)Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: SI

Photos

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE
330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

KIA
Movement that inspires

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 TEL: 67143369 Contact No	Cust No/Name /Ms Kum Woon Yiong Serena Reg No/Reg Date SMJ2665L / 27/02/2019 Date In/Mileage 30/05/2022/ 35225 Chassis No KNAF3416MK5024856 Engine No G4FGJH713650 Make/Model KIA/CER1.6ASXG335 Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000051	Credit	01/06/2022/ 08:24	DS	303 / Renemer	29946				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	DIAGNOSTIC/SCANNING							250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS							80.00
S	MIPNT88088	TO REPLACE KIA LOGO,UPR & LWR FRONT BUMPER.CLIPS,BRACKETS RH T/SIGNAL LAMP COVER. STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS							640.00
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS (UPPER FRONT BUMPER)							550.00
X	KS 86318 3R 500	ORNAMENT - KIA NO. 1	1.00	38.00	0.00			38.00	
X	KS 86511 M6 000	UPR COVER-FRONT BUMP	1.00	633.00	0.00			633.00	
X	KS 86530 M6 160	LWR GRILLE-FRONT BUM	1.00	485.00	0.00			485.00	
X	KS 0G032 50 037A	FASTER- BUMPER	10.00	2.00	0.00			20.00	
X	KS 86551 M6 000	LH SIDE UPR BRACKET-	1.00	22.00	0.00			22.00	
X	KS 86552 M6 000	RH SIDE UPR BRACKET-	1.00	22.00	0.00			22.00	
X	KS 86594 M6 120	RH MOULDING-FRONT BU	1.00	216.00	0.00			216.00	
Z	NOTES	ACCIDENT ON 17/02/2022 ALONG 153 KAMPONG AMPAT JUNJIE BLDG S368326 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT TP#: GBG1307Z TP INS: ALLIANZ							
Z	NOTES	FINALIZATION (NO. OF TOTAL REPAIR DAYS - 3 DAYS) ATTENTION TO: MR. THEVAN							

Confirm & accepted by

F: 2456
RD: 4

Parts	1,436.00
Labour	0.00
Standard Menu	0.00
Specialist Job	1,520.00
Others (Lub, etc)	0.00
Sundry	0.00
Total (w/o GST)	2,956.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 732C

Vehicle Details

Vehicle No.: SMJ2665L
Vehicle to be Exported: No
Intended Deregistration Date: 19 Jul 2022
Vehicle Make: KIA
Vehicle Model: CERATO 1.6(A) SX
Primary Colour: Silver
Manufacturing Year: 2018
Engine No.: G4FGJH713650
Chassis No.: KNAF3416MK5024856
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$17,798.00
Original Registration Date: 27 Feb 2019
First Registration Date: 27 Feb 2019
Transfer Count: 0
Actual ARF Paid: \$17,798.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Feb 2029
PARF Rebate Amount: \$13,348.00

Intended COE Rebate Details

COE Expiry Date: 26 Feb 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$25,920.00
COE Rebate Amount: \$17,118.00
Total Rebate Amount: \$30,466.00

The information contained herein is correct as at 19 Jul 2022

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertisement Length Ways of Selling

Latest Facelift! Priced to sell! Flexible financing



1.6L engine
100% loan available



Sort by Date Posted 20 results/page

9 vehicles



Cerato 1.6A SX

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Cerato 1.6A SX		Any	Any	2019	Any	Any	Any	Available
	Kia Cerato 1.6A SX Sunroof		\$87,800	\$11,660 /yr	12-Apr-2019	1,591 cc	49,867 km	Sedan	Available
Comes with agent warranty till Apr 2024 for peace of mind! Stylish and reliable Korean sedan with 1.6L engine providing you adequate p...									
Sime Darby Auto Selection									
Posted: 19-Jul-2022									
	Kia Cerato 1.6A SX Sunroof		\$91,000	\$12,580 /yr	25-Jan-2019	1,591 cc	-	Sedan	Available
Well Maintained By Previous Owner With No Expense Spared! Guaranteed Accident Free With Good Running Engine & Interior Condition...									
Posted: 16-Jul-2022									
	Kia Cerato 1.6A SX Sunroof		\$92,800	\$12,110 /yr	07-Jun-2019	1,591 cc	42,000 km	Sedan	Available
Pristine Condition! 1 Owner! Low Mileage! Agent Unit, Full Service Done At C&C! 100% Loan Available With Low Interest Rate From 1.88...									
This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More									
Platinum Motoring									
Posted: 15-Jul-2022									
	Kia Cerato 1.6A SX Sunroof		\$91,800	\$12,480 /yr	26-Feb-2019	1,591 cc	29,000 km	Sedan	Available
B942.1 Owner Unit! Fully Serviced By C&C, Still Under Agent Warranty! SX Specs With Electric Seats And Sunroof! Smart Trunk & Parking...									
Posted: 12-Jul-2022									
	Kia Cerato 1.6A SX Sunroof		\$96,800	\$12,040 /yr	15-Oct-2019	1,591 cc	31,277 km	Sedan	Available
Certified Pre-Owned, Drive With Peace Of Mind, Enjoy 1 Year Extended Warranty And 2 Years Servicing As Standard. 1 Owner Car, Car St...									
Republic Auto									
Posted: 12-Jul-2022									
	Kia Cerato 1.6A SX Sunroof		\$92,800	\$12,000 /yr	02-Jul-2019	1,591 cc	46,890 km	Sedan	Available
Peace of mind with C&C certified pre-owned, Strict Inspection process done to qualify as a cpo. Call for an exclusive viewing. Low interes...									
Republic Auto									
Posted: 09-Jul-2022									
	Kia Cerato 1.6A SX Sunroof		\$91,800	\$12,190 /yr	24-Apr-2019	1,591 cc	43,000 km	Sedan	Available
Superb Condition, SX Specs With Electric Seats And Sunroof, Well Taken Care Of, C&C Unit, 10 Years Engine Warranty, 2.28% Loan Inter...									
Posted: 04-Jul-2022									
	Kia Cerato 1.6A SX		\$85,800	\$11,550 /yr	08-May-2019	1,591 cc	-	Sedan	Available
1 Owner, Facelift Model, High Spec Edition With Led Headlight, Most Demand Metallic Pearl White With Premium Leather Interior, 100% Acc...									
Pte Ltd									
28-Jun-2022									

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 TEL: 67143369 Contact No	Cust No/Name /Ms Kum Woon Yiong Serena Reg No/Reg Date SMJ2665L / 27/02/2019 Date In/Mileage 17/05/2022/ 34613 Chassis No KNAF3416MK5024856 Engine No G4FGJH713650 Make/Model KIA/CER1.6ASXG335 Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000051	Credit	18/05/2022/ 14:48	DS	303 / Renemer	29946			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING						250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS						80 100.00
S	MIPNT88088	TO REPLACE KIA LOGO,UPR & LWR FRONT BUMPER.CLIPS,BRACKETS,RAD GRILLE, RH T/SIGNAL LAMP & MLG,ENERGY ABSORBER,REINFORCEMENT,WASHER TANK,ETC STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS						640 1280.00
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS						550 1100.00
M	KS 86318 3R 500	ORNAMENT - KIA NO. 1			1.00	38.00	0.00	38.00
M	KS 86511 M6 000	UPR COVER-FRONT BUMP			1.00	633.00	0.00	633.00
M	KS 86530 M6 160	LWR GRILLE-FRONT BUM			1.00	485.00	0.00	485.00
M	KS 06032 50 037A	FASTERNER-BUMPER			10.00	2.00	0.00	20.00
M	KS 86551 M6 000	LH SIDE UPR BRACKET-			1.00	22.00	0.00	22.00
M	KS 86552 M6 000	RH SIDE UPR BRACKET-			1.00	22.00	0.00	22.00
M	KS 86594 M6 120	RH MOULDING-FRONT BU			1.00	216.00	0.00	216.00
M	KS 92304 M6 000	RH LAMP ASSY-SIDE RE			1.00	164.00	0.00	164.00
M	KS 99310 M6 000A HV	ULTRASONIC SENSOR AS			4.00	163.00	0.00	652.00
M	KS 86350 M6 010	GRILLE ASSY-RADIATOR			1.00	328.00	0.00	328.00
M	KS 86520 M6 000	ABSORBER-FRONT BUMPE			1.00	84.00	0.00	84.00
M	KS 64900 M6 000	BEAM COMPLETE-FR BUM			1.00	497.00	0.00	497.00
M	KS 98610 M6 100	RESERVOIR & PUMP ASS			1.00	146.00	0.00	146.00
Z	NOTES							
ACCIDENT ON 17/02/2022 ALONG 153 KAMPONG AMPAT JUNJIE BLDG S368326								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT								
TP#: GBG1307Z TP INS: ALLIANZ								
Thuan @ 24 hours - low 82235769 24/5/22 p/p 4 days wp								
Confirm & accepted by					Kia Auto Consistants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: 3,307.00			
Authorized signatory and company stamp					Labour 0.00 Standard Menu 0.00 Specialist Job 2,730.00 Others(Lub,etc) 0.00 Sundry 0.00 Total(w/o GST) 6,037.00			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.