

ASS. REC. BY: Form

REF:

CS3/ASM 2200 4856/Rvg³

0416

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 8739Pat Workshop m/s A-TU AUTOMOTIVEof 39, WOODMAN'S CLOSE #02-43 @ MHAInsured: SHB 6620R AXA

Policy No. _____


Claims No. S2M041UD

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 83k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF 8739P Yr Regn: 2018 / MVType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 3 SEDAN 1.5 AT S/R 1496Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 73456 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 6BN 22A 8K 0251102Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/R / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/05/22D.O.I. 23/05/22Survey held at A-TUDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 53K

25/5/22

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (4K 5K) / 6 days

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 25/5/22-typist

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

\$ + RS. \$ _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

Report Format: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	041G
Vehicle No.:	SMF8739P
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	P520550257
Chassis No.:	JM6BN22A8K0251102
Maximum Power Output:	88.0kW (118 bhp)
Open Market Value:	\$14,466.00
Original Registration Date:	28 Nov 2018
First Registration Date:	28 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$14,466.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2028
PARF Rebate Amount:	\$10,849.00
COE Expiry Date:	27 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,199.00
COE Rebate Amount:	\$18,352.00
Total Rebate Amount:	\$29,201.00

The information contained herein is correct as at 24 May 2022

OK

Mazda 3 1.5A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$83,800		
Depreciation 	\$11,810 /yr View models with similar depre	Reg Date	15-Nov-2018 (6yrs 5mths 21days COE left)
Mileage	26,500 km (7.5k /yr)	Manufactured 	2018
Road Tax 	\$682 /yr	Transmission	Auto
Dereg Value 	\$29,129 as of today (change)	OMV 	\$14,466
COE 	\$28,199	ARF 	\$14,466
Engine Cap	1,496 cc	Power	88.0 kW (118 bhp)
Curb Weight 	1,310 kg	No. of Owners 	1
Type of Vehicle	Mid-Sized Sedan		