

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE		Ref:	CS3/ASM22004886/Rqy3e2		
	8 SHENTON WAY SINGAPORE 0688		Date:	01/06/2022		
	ATTN: KHONG LYI	NN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMW 5952U	Veh. Inspected	l	SMU 8586J	
	Policy No.	GA603359	Coverage (\$)		0.00	
	Claim No.	S2M041YC	Excess (\$)		0.00	
	Assign From	KHONG LYNN	Assign Date		24/05/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ AMG A45 S 4M S/R	c.c		1991	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	W1K1770542N153911	Colour		GREY	
	Odometer	19447 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/35Z R19	MICHELIN		6 mm	
	L/H Front Tyre	245/35Z R19	MICHELIN		6 mm	
	R/H Rear Tyre	245/35Z R19	MICHELIN		6 mm	
	L/H Rear Tyre	245/35Z R19	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTIO			N.		
5.	General Information					
	Accident Date	21/05/2022	Inspect Date /	Time	25/05/2022 (04:34 PM)	
	Survey held at	SZE KANG AUTOMOBILE SPRAYING SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT SINGAPORE 568047				
5a.		Remarks				
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLI	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	•					

Report Ref No. CS3/ASM22004886/Rqy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

RECO Auto Consultant OAE Licensed American

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$