

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI22004901/Uty3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 02/06/2022	
			Cod	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SND 9205E	Veh. Inspected	SLC 7543X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10015362/CH	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	24/05/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU11115079	Colour	WHITE	
	Odometer	168903 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	19/05/2022	Inspection Date	24/05/2022	
	Survey held at 15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ				
	Repairer ASIA MOTORSPORTS SOLUTION PTE LTD				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: