

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ N/S / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s AUTO BEST

of

Insured:

Policy No:


Claims No. SNM22D203537/C02

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$11k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMK3926Y

Yr Regn: 14 Apr/2009

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI HD AVANTE 1.6 c.c 1591

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 242495

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMH DU41BR9U727164 *

Gen. Cond ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size: F: 195/65R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GITI

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 24-05-2022

Survey held at

W/S

5:30PM

Des. of Damages: ☒ Frt ☒ Rea ☐ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$5000 - \$6000
	COE Expiry Date :13 Apr 2024
	Total Rebate Amount \$4,935
25/05/22	Submit PRS.

Date/Time, File Pass to?

☐ : Preli. Report

1) 25/05 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

S + RS. SI

Photos

Other:

TOTAL

Report Filed: MER-PRS

Long Code/MPB: