

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

79 ROBINSON ROAD #09-01 SINGAPORE 068897 Code: AIS Policy Particulars :- THIRD PARTY CLAIM	004905/Uqy3n2 2	
#09-01 SINGAPORE 068897 Code: AIS Policy Particulars :- THIRD PARTY CLAIM	2	
1. Policy Particulars :- THIRD PARTY CLAIM		
,		
L LUL VD TOOOD	1. Policy Particulars :- THIRD PARTY CLAIM	
Insured Veh. XD 7832P Veh. Inspected SKE 8875H	4	
Policy No. Coverage (\$) 0.00		
Claim No. 800SWAISCL2022-0110FR Excess (\$) 0.00		
Assign From SHANTI Assign Date 24/05/2022	2	
2. Vehicle Particulars & Condition		
Make & Model MAZDA 6 (A) c.c 1998		
Engine No. HIDDEN Year of Reg. 2020		
Chassis No. JM6GL1072K0321565 Colour GREY		
Odometer 24226 KM Steering IN ORDEI	R	
Brakes IN ORDER Modification SPORTS R	RIM	
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 225/55 R17 BRIDGESTONE 6 mm		
L/H Front Tyre 225/55 R17 BRIDGESTONE 6 mm		
R/H Rear Tyre 225/55 R17 BRIDGESTONE 6 mm		
L/H Rear Tyre 225/55 R17 BRIDGESTONE 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 21/05/2022 Inspection Date 24/05/2022	2	
Survey held at FASTECH AUTO PTE LTD		
1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days		