

ASS. REC. BY:

REF:

C72 / 22004907 / kgv3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

SNM22D203574 / CO2

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

21/6 @ 450.60 Cnkr (rest @ 28.40, 6%)

21/6/22 @ 10.33am referred to Billy Tan via Netimen.

Date/Time, File Pass to?

1) 21/6 10:33am

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Report Format:

MER-TP

Lump Sum / I.B.I. (\$)

450.60

Days of Repair:

2

Reserve No. of Trip:

1

Add Fee:

☐ Ins (\$)☐ View (\$)☐ Invs (\$)☐ Road (\$)

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

TOTAL

VIN:

GRB6 28866 / Reg: OF 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Police Mover /

Truck / Trailer or

Toy Dyna

2982

Color:

White

A/C: Insured / Std / NI / NA

Sealing:

79685

T/Radio: Insured / Std / NI / NA

No:

C/N:

JTFA T35 Y Fok 208 254

Cond: Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Tire: All / S/Rim / STD A/Rim or

Size:

F: B.S

195R15X8

R: Yoko

155R12X80D

EXNOVA / GY / FS / LIZA / MIC / OHTSU / R / SUMI /

YOKO or

Front:

9

mm

Rear:

9

mm

Side:

9

mm

L/Bal:

9

mm

Date:

23/5/22

D.O.I.

16/6/2022

Insured at:

Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

U/C / Chassis frame / Body Structure affected due to collision.

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-SMJ 7594A
Repairer Reference: 72712
Date calculated: 24/05/2022 2:48 PM

Full Report
Registration: GBG 2866U
Printed: 24/05/2022 2:49 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-SMJ 7594A	Date of Incident:	23/05/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	DYNA		
Sub Model:	150		
Model Sheet Number:	70 1N 03		
Registration:	GBG 2866U		
VIN number:			
Odometer:	77236		
Model Specs			
FROM 02.2011	AIR CONDITIONING	SINGLE CAB	3.0 LTR 80KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

*Not Notified
 Repair After Repair
 2 days*

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
1003	LH T-LAMP PANEL REPAIR		15 20.0 *	84.00
	Labour Cost		Hrs	WU
	Panel / Mechanical Labour		2.00	20.0
	Total of Labour			84.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC		WU Price SGD
	SAFETY BAR + LH T-LAMP PNL		180 200.00*

Audatex System Using Manufacturer Times

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 2

Acknowledged by Repairer
 Signature: _____
 Date: _____

PRINT DATE 24/05/2022

Labour Cost - Paint

Time Paint

Total

Hrs

WU

Price SGD

10 WU/h

200.00

Extras

Code	Description	Price SGD
1000	REAR NUMBER PLATE	20.00*
1001	BLACK/WHITE TAPE 1.2M	30.00*
1002	BLACK/YELLOW TAPE 1.5M	40.00*
Total Extras		90.00

Final Calculation


	SGD	SGD
Labour Time Base 10 WU/h		
Total 20.0 WU X 42.00 SGD/h	84.00	
Total of Labour		84.00
Total Of Extras		90.00
Paint Work Time Base 10 WU/h		
Total Paint Fixed Labour	200.00	
Total Paint Including Material		200.00
Repair Cost Excludes GST		374.00
GST (+7.0%)		26.18
Repair Cost Included GST		400.18

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-SMJ 7594A
 Repairer Reference: 72712
 Date calculated: 17/06/2022 4:35 PM

Full Report
Registration: GBG 2866U
Printed: 17/06/2022 4:35 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-SMJ 7594A	Date of Incident:	23/05/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	DYNA		
Sub Model:	150		
Model Sheet Number:	70 1N 03		
Registration:	GBG 2866U		
VIN number:			
Odometer:	77236		
Model Specs			
FROM 02.2011	AIR CONDITIONING	SINGLE CAB	3.0 LTR 80KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
811011	R + R LEFT TAIL LAMP		3.0	12.60
1003	L/TAILLAMP PANEL REPAIR		15.0*	63.00
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	1.80	18.0	75.60
	Total of Labour			75.60

Paint

		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC		WU Price SGD
	SAFETY BAR + L/TAILLAMP PNL		180.00*

Labour Cost - Paint		Hrs	WU	Price SGD
Time Paint				
Total	10 WU/h			180.00

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
3281	L/R LAMP ASSY	81560 37062	Original	CM 105.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			105.00
u: Used parts	Total			105.00

Extras

Code	Description	Price SGD
1000	REAR NUMBER PLATE	20.00*
1001	BLACK/WHITE TAPE 1.2M	30.00*
1002	BLACK/YELLOW TAPE 1.5M	40.00*
Total Extras		90.00

Final Calculation

	SGD	SGD
Parts	105.00	
Total Parts		105.00
Labour Time Base 10 WU/h		
Total 18.0 WU X 42.00 SGD/h	75.60	
Total of Labour		75.60
Total Of Extras		90.00
Paint Work Time Base 10 WU/h		
Total Paint Fixed Labour	180.00	
Total Paint Including Material		180.00
Repair Cost Excludes GST		450.60
GST (+7.0%)		31.54
Repair Cost Included GST		482.14

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/05/2022 13:45 (SGT)
Date of Accident	23/05/2022 10:40 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	towards Kallang Way
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG2866U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	The Mill International Pte Ltd
Company Reg No	1XXXXX000H
Email Address	william.cheng@themill-int.com
Mobile Phone No	(Phone) +65-97971270
Alternative Phone No	+65-97971270

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2952

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070086919-01
Cover Note Number	-

DRIVER

Name of Driver	Qiao Hongliang
Passport No/FIN	GXXXX999N

Date Of Birth	12/09/1978
Occupation	Outdoor
Date Of Driving Pass	04/02/2016
Driving experience	6 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90096012
Alt. Phone Number	-
Email Address	william.cheng@themill-int.com
Address	5 Lorong 12 Geylang
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Hamzah
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

On 23rd May 2022 at around 10.40 am, I was driving my company lorry no. GBG 2866U along PIE towards Kallang Way. There was a car suddenly cut into the lane and caused the car in front of me to e-brake. Upon seeing it, I quickly jammed my brake and manage to stop in time without hitting the car in front of me. The car no. SMJ 7594A which was behind me unable to stop in time and collided onto the rear of my lorry, the impact was great and caused my lorry to surge forward but did not hit any car. There was another car no. SLQ 2990Y hit the rear of SMJ 7594A. We exchanged particulars and left the scene. After the accident, I fell unwell and went to see a doctor. I was given 2 days MC.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMJ7594A
Vehicle Manufacturer	Honda

Vehicle Model	Freed
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Wu Junxian, Kenneth
NRIC No	SXXXX937I
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLQ2990Y
Vehicle Manufacturer	Toyota
Vehicle Model	Prius
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	Teo Chin Choon
NRIC No	SXXXX770D
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Qiao Hongliang
Gender	Male
Phone No	(Phone) +65-90096012
Address	5 Lorong 12 Geylang
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	GBG2866U
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &
Time 24 May 2022

Driver's Signature (If driver is not the policyholder) / Date
& Time 24 MAY 2022

Witnessed by Reporting Centre
Personnel Jenny Lim

Sketch Plan

A - GBG 28664
B - SMJ 7594-A
C - SLQ 2990Y



Describe Circumstances of the Accident

On 23rd May 2022 at around 10:40 am, I was driving my company lorry no. GBG 2866U along PIE towards Kallang Way. There was a car suddenly cut into the lane and caused the car in front of me to e-brake. Upon seeing it, I quickly jammed my brake and manage to stop in time without hitting the car in front of me.

The car no. SMJ 7594A which was behind me unable to stop in time and collided onto the rear of my lorry, the impact was great and caused my lorry to surge forward but did not hit any car. There was another car no. SL9 2990Y hit the rear of SMJ 7594A. We exchanged particulars and left the scene.

After the accident, I fell unwell and went to see a doctor. I was given 2 days MC.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
24 May 2022




Driver's Signature (If driver is not the policyholder) / Date & Time
24 MAY 2022


Witnessed by Reporting Centre Personnel
Jenny Lim



CERTIFICATE OF INSURANCE

COMMERCIAL AUTOPLUS COMMERCIAL VEHICLE

Name of Policyholder : THE MILL INTERNATIONAL PTE LTD
Period of Insurance : 10 Jul 2021 To 09 Jul 2022
Engine No. : 1KD2713556
Chassis No. : JTFAT35Y70K208254

Vehicle No. : GBG2866U
Policy No. : 2070086919-01
Endorsement No. :
Issued Date : 18 Jun 2021

ABOUT THE COVER

Make/Model : TOYOTA DYNA 150D 1.4 ton [Lorry]
Engine Capacity/Tonnage : 1.4 Tonnage
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) Any person who is driving on the Policyholder's order or with their permission.
b) This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

- 1) Use in connection with the Policyholder's business.
2) Use for the carriage of passenger (other than for hire or reward) in connection with the Policyholder's business.
3) Use for social, domestic or pleasure purposes. This Policy does not cover a) use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing; and b) use whilst drawing a trailer except the towing of anyone disabled using a mechanically propelled vehicle. c) use for any purpose in connection with Motor Trade.

Loss Of Use (7 Days) Commercial Auto

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Maybank Singapore Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504592000

INSURE U SERVICES

9 LORONG 27A GEYLANG #02-13

SINGAPORE 388134

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

june.koh@insureu.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	000H

Vehicle Details

Vehicle No.:	GBG2866U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2713556
Chassis No.:	JTFAT35Y70K208254
Maximum Power Output:	-
Open Market Value:	\$26,436.00
Original Registration Date:	10 Jul 2017
First Registration Date:	10 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,322.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	09 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$18,897.00
Total Rebate Amount:	\$18,897.00

The information contained herein is correct as at 24 May 2022

OK


INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

SMJ7594A

Date of Accident

23/05/2022 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance China Taiping Insurance (Sing...

Period of Insurance 30/09/2021 - 29/09/2022

Requested By Jenny Lim (Lai Huat (Meng Ke...

Requested Date 24/05/2022 10:45

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**