

ASS. RE. BY:

Tough

REF:

CS6/AS2200 4909/T43.

ASSIGNMENT

Lot 2030 Dec.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. **2022 22004895FR**Sum Insured: _____ Excess: **1000**

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **775K**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SMC2504E** Yr Regn: **2010 / Dec.**

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Volkswagen Scirocco 1.4cc 1390**Colour: **blue** A/C: Insured / Std / NI / NASp. Reading: **187377** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WVWZZZ15ZBV01533**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **235/45R19**R: **N**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal. **6** mmL/Bal. **6** mm

D.O.A. _____

Survey held at

Success United

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. **6** mmL/Bal. **6** mmD.O.I. **25/5/22**

Date / Time Action / Instruction

confirmed L/S \$3,800.00 with 5 repair days.**red: 3722.30,49%**

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B. (\$) _____

Days Of Repair: **5**

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

SUCCESS UNITED PTE LTD

Page 1 / 2

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

Allianz Insurance (S) Pte Ltd
3 Temasek Ave #09-01 Centennial Towers
Singapore 039190

Attention : Motor Claim Department

Contact : 62972529

Estimate : SU220053

Date : 20/05/2022

Vehicle Num. : SMC2504E

Make/Model : Volkswagen Scirocco-2010

Chassis/Eng# : WVVZZZ13ZBV015332/CAV233249

Accident Date : 17/05/2022

Claim No. :

Reference :

Policy No. : SP2000700564 (15/12/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 pc	Frt Bonnet		680.00 bt✓
2.	1 pc	Frt Bonnet Hinge LH		65.00 XNA
3.	1 pc	Frt Bonnet Mechanism Lock		150.00 XNA
4.	1 pc	Frt Fender LH		390.00 bt✓
5.	1 pc	Frt Fender Inner Panel LH		1,200.00 RP
6.	1 pc	Frt Fender Inner Liner LH		120.00 de✓
7.	1 pc	Frt Bumper Assy		650.00 in✓
8.	1 pc	Frt Bumper Side Holder LH		28.00 de✓
9.	1 pc	Frt Bumper Bracket LH		30.00 XNA
10.	1 pc	Frt Bumper Inner Sponge		120.00 ? cur✓
11.	1 pc	Frt Bumper Reinforcement		350.00 ? bt✓
12.	1 pc	Frt Bumper Foglamp LH		150.00 ? cur✓
13.	1 pc	Frt Bumper Foglamp Garnish LH		125.00 de✓
14.	1 pc	Frt Bumper Signal Lamp LH		95.00 cut✓
15.	1 pc	Frt Bumper Lower Centre Air Grille		170.00 cut✓
16.	1 pc	Frt Grille Assy		200.00 cut✓
17.	1 pc	Headlamp Assy LH		490.00 cur✓
18.	1 pc	Headlamp Panel LH		110.00 bt✓
19.	1 pc	Horn		70.00 XNA
Total Parts Purchased S\$:			3678	5,193.00
10.00% Of The Above Parts S\$:				519.30
Based On Cost Plus S\$:			+ 10% - 367.80	5,712.30
SPECIAL NETT ITEMS :			4045.80	
1.	1 set	Frt Fender Inner Liner Clips		30.00 Zone✓
2.	1 set	Frt Bumper Clips		30.00 net✓
Special Nett Total S\$:				60.00
				50

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Allianz Insurance (S) Pte Ltd
3 Temasek Ave #09-01 Centennial Towers
Singapore 039190

Attention : Motor Claim Department

Contact : 62972529

Estimate : SU220053

Date : 20/05/2022

Vehicle Num. : SMC2504E

Make/Model : Volkswagen Scirocco-2010

Chassis/Eng# : WWWZZZ13ZBV015332/CAV233249

Accident Date : 17/05/2022

Claim No. :

Reference :

Policy No. : SP2000700564 (15/12/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting	150.00	30
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	800.00	600
		To putty and respray painting on affected area.	800.00	700
		Labour Total S\$:	1,750.00	1330

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjiu 92495749/62563561
20/5/22 21045

Ex: tba, Not Authorise

05 days

Lumpsum, Resurvey after repair

tanjiu@lkkauto.com

SUCCESS UNITED PTE LTD

Total S\$: 7,522.30

=====

4045.80

50

1330

5425.80

41584300 #

05 days