



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2203747

INV Date 16/06/2022

Reference CS/EQI22004914/Ety3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SW 54Z

Insured Veh. SLS 9464T

Claim No. DM22HO00784

Policy No.

Accident Date 14/05/2022

Inspection Date 25/05/2022

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS/EQI22004914/Ety3e2 Date: 16/06/2022 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLS 9464T	Veh. Inspected	SW 54Z
Policy No.		Coverage (\$)	0.00
Claim No.	DM22HO00784	Excess (\$)	0.00
Assign From	NEO JIE SI	Assign Date	20/05/2022
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 330i	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WBA5R12000AK72151	Colour	GREY
Odometer	23336 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	DUNLOP	4 mm
L/H Front Tyre	225/45 R18	DUNLOP	4 mm
R/H Rear Tyre	225/45 R18	DUNLOP	4 mm
L/H Rear Tyre	225/45 R18	DUNLOP	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/05/2022	Inspection Date	25/05/2022
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SW 54Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
2	EXPANDING NUT (SN)	NOT NECESSARY	1.30	-
2	PLASTIC INSERT BOLT (SN)	NOT NECESSARY	3.20	-
2	FILLISTER HEAD SCREW (ISA) (SN)	NOT NECESSARY	6.30	-
1	RR BUMPER CARRIER (SN)	NOT NECESSARY	446.75	-
1	RR BUMPER CTR GUIDE (SN)	NOT NECESSARY	138.15	-
1	PDC HOLDER INSIDE LH (SN)	NOT NECESSARY	10.15	-
1	PDC HOLDER OUTSIDE LH (SN)	NOT NECESSARY	11.65	-
1	PDC HOLDER OUTSIDE RH (SN)	NOT NECESSARY	11.65	-
1	RR BUMPER CTR BOTTOM GUIDE (SN)	NOT NECESSARY	65.80	-
1	RR BUMPER (PDC) (SN)	DENTED	1,176.40	1,281.15
1	RR BUMPER TOW HOOK COVER (SN)	NOT NECESSARY	39.35	-
2	RR BUMPER BREATHER COVERING (SN)	NOT NECESSARY	113.60	-
1	EXH. EXTNSION (SN)	NOT NECESSARY	24.25	-
			2,128.55	1,361.15
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER.		1,275.00	850.00
	TO RESPRAY REAR BUMPER AND AFFECTED AREAS.		1,038.00	986.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
	TO CHECK ELECTRICAL WIRING SYSTEM.		177.00	168.00
			2,667.00	2,172.00
	GRAND TOTAL		4,795.55	3,533.15
	RECOMMENDED COST OF REPAIRS			3,533.15

Report Ref No. CS/EQI22004914/Ety3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/05/2022 12:38 (SGT)
Date of Accident	14/05/2022 08:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TAMPINES AVE 7 & STREET 45 JUNCTION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SW54Z
-----------------------------	-------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KOH SHIN HOW
NRIC No	SXXXX668H
Email Address	COLD.VINCE@GMAIL.COM
Mobile Phone No	(Phone) +65-90016015
Alternative Phone No	(Home) +--

VEHICLE PARTICULARS

Manufacturer	BMW
Model	330i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	Etiqua Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	CN008001

DRIVER

Name of Driver	KOH SHIN HOW
NRIC No	SXXXX668H



Date Of Birth	30/06/1978
Occupation	Indoor
Date Of Driving Pass	24/06/1996
Driving experience	25 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90016015
Alt. Phone Number	(Home) +--
Email Address	COLD.VINCE@GMAIL.COM
Address	BLK 60 FLORA DRIVE
Address complement	#02-37
Postcode	506858
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	KOH QIAN XI
Gender	Female

PASSENGER 2

Name	KOH CHENG XI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS9464T
Vehicle Manufacturer	Audi

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Red
Vehicle Category	Private car
Name of Driver	ASRI BIN YUNUS
NRIC No	SXXXX820D
Contact Number	(Phone) +65-96649706
Address	64 FLORA DRIVE
Address complement	#03-49
Postcode	506860
Insurance Company Name	-
Nature Of Damage	FRONT
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 14/5/22 12:00h

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name: Yap mee key

NRIC/FIN No.: 92744029P

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am driving on Tampines Ave 7 towards tampine central. At around 8.50 am at Junction Tampines Street 34, I was waiting for the red light to turn green. While waiting for about 1 min suddenly a red Audi car SLS 9464 bang to my rear bumper with a loud bang. (Photos Attached)

As both of us is rushing for appointment, ~~the~~ the owner agreed to bear the damage with what's app agreement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

14 May 22
1156 am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

me

Reporting Centre Personnel's Signature

Name: Yap mee kay

NRIC/FIN No.: 62744629P



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SW 54Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SW 54Z

RE-INSPECTION

