

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. SNM22D203575/C02
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SNC 6396L Yr Regn: 27/8/21
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Skoda Octavia c.c. 1198
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 12798 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: TM BBR 7N X 6 M V 179598
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jaimmed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. of Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 205/55R17
 R: _____
 BS / DUN / EXNOVA FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 23/5/22 D.O.I. 26/5/22
 Survey held at Volkswagen
 Des. of Damages: Rear RH / Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|--------------------------|--|
| | <u>MV-1472</u> |
| <u>31/05/22 @ 5.25pm</u> | <u>revised to Adeline Chng via Merimen.</u> |
| | <u>Steve finalised final fig \$5614.01, 4 days. (Red \$4970.63, 47%)</u> |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 28/06 Typist
 Date/Time, File Return to?
 2) _____
 Report Format: _____
~~Temp. Sum.~~ / I.E.I. (\$) 5614.01

Days Of Repair: 4
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____
 Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____

SKODA Centre Singapore

Leng Kee Rd
Singapore 159104
Tel. Reg. No.: 1991014942
GST No.: M200985052



Steve (LKR)
26/5/22, 9.30am
ML AL
4 days
PIA
ly PL ly

Quotation
Non binding - Preview

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
ONG
BOON LEONG
23 SIN MING ROAD
#12-07
SINGAPORE 570023

Page 1/2
Document no.
Document date 24-05-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022014932/ 1
Job order date 24-05-2022
Service Advisor SHU SHI TANG

| | | | | | |
|---------------------------|------------------------|----------------------------------|--------------------------|---|-------------------|
| License plate SNC6396L | Model code NX33JDA1 | First registration 27-08-2021 | VIN TMBBR7NX6MY179598 | Model Octavia Amb 1.5 TSI 110kW e-TEC DSG MY21 | Mileage 11,879 |
|---------------------------|------------------------|----------------------------------|--------------------------|---|-------------------|

| Position no. | Description | Quantity | Unit | Unit price excl. GST | Tax code | Total amount excl. GST | Total amount incl. GST |
|--------------|--|----------|------|-------------------------|---------------|---------------------------|---------------------------|
| 9801B004 | B&P CHECK SHORT CIRCUIT/HARNESS REPAIR | | | | #1 | 280.00 | 299.60 |
| 9801B005 | B&P DIAGNOSIS AND PROGRAMMING | | | | #1 | 480.00 | 513.60 |
| 9801B003 | B&P WHEEL ALIGNMENT | | | | #1 | 360.00 | 385.20 |
| 9801B001 | R&R RIM & BALANCE | | | | #1 | 50.00 | 53.50 |
| 9801B001 | R&R REAR WHEEL BEARING | | | | #1 | 840.00 | 898.80 |
| 5E6807421 | Unbekannt REAR BUMPER <i>CRU</i> | 1 | pcs. | 1,635.95 | #1 | 1,635.95 | 1,750.47 |
| 5E7919485A | Unbekannt SENSOR BRACKET <i>AL</i> | 1 | pcs. | 16.33 | #1 | 16.33 | 17.47 |
| 5E6919485 | Unbekannt SENSOR BRACKET <i>AL</i> | 1 | pcs. | 16.33 | #1 | 16.33 | 17.47 |
| 5E6919486 | Unbekannt SENSOR BRACKET <i>AL</i> | 1 | pcs. | 16.33 | #1 | 16.33 | 17.47 |
| 5E7919486A | Unbekannt SENSOR BRACKET <i>AL</i> | 1 | pcs. | 16.33 | #1 | 16.33 | 17.47 |
| 5E7807394 | Unbekannt RHR BUMPER BRACKET (SIDE) ? | 1 | pcs. | 43.21 | #1 | 43.21 | 46.23 |
| 5E6807378 | Unbekannt RHR BUMPER BRACKET (UPPER) ? | 1 | pcs. | 64.48 | #1 | 64.48 | 68.99 |
| 5E7945106 | Unbekannt RHS REFLECTOR X | 1 | pcs. | 59.81 | #1 | 59.81 | 64.00 |
| 6R0819465C | Vent Trim RHR FENDER AIR DUCT ? | 1 | pcs. | 42.93 | #1 | 42.93 | 45.94 |
| 5E3819164 | Unbekannt AIR DUCT COVER ? | 1 | pcs. | 49.52 | #1 | 49.52 | 52.99 |
| 5E3601025E | Unbekannt RIM <i>CUT</i> | 1 | pcs. | 1,098.89 | #1 | 1,098.89 | 1,175.81 |
| 311601361 | Rubber Valve <i>AL</i> | 1 | pcs. | 3.85 | #1 | 3.85 | 4.12 |
| 5WA501611 | Wheel Hub With Bearing | 1 | pcs. | 569.90 | #1 | 569.90 | 609.79 |
| WHT007150 | Shouldered Bolt <i>AL</i> | 1 | pcs. | 11.33 | #1 | 11.33 | 12.12 |
| 1J0501249C | Cap X | 1 | pcs. | 9.45 | #1 | 9.45 | 10.11 |
| | LABOUR | 21 | pcs. | 840.00 | #1 <i>840</i> | 2,520.00 | 2,696.40 |
| | SPRAY PAINT | 21 | pcs. | 800.00 | #1 <i>800</i> | 2,400.00 | 2,568.00 |
| | CHINA TAIPING DIRECT DOA: 23/05/2022 TP VEH: SMU112X SURVEY BY: | | | | | | |

Quotation valid till 31-05-2022

| Tax Code | Labour | Material | GST % | GST | Total amount excl. GST | Total amount incl. GST |
|----------|----------|----------|-------|--------|---------------------------|---------------------------|
| #1 | 2,010.00 | 8,574.64 | 7% | 740.92 | 10,584.64 | 11,325.56 |

JDA Centre Singapore
 150 Selegie Rd
 Singapore 159104
 Reg. No.: 199101494Z
 UEN No.: M200985052



Quotation
 Non binding - Preview

Page 2/2

Company
 CHINA TAIPING INSURANCE (S) PL
 3 ANSON ROAD
 #18-00 SPRINGLEAF TOWER
 Singapore 079909

Customer Details:
 Mr
 ONG
 BOON LEONG
 23 SIN MING ROAD
 #12-07
 SINGAPORE 570023

Document no.
 Document date 24-05-2022
 Customer no. 5211001170
 Customer GST-ID 200208384E
 Dealer 30001
 Job order number 2022014932/ 1
 Job order date 24-05-2022
 Service Advisor SHU SHI TANG

| License plate | Model code | First registration | VIN | Model | Mileage |
|---------------|------------|--------------------|-------------------|--|---------|
| SNC6396L | NX33JDA1 | 27-08-2021 | TMBBR7NX6MY179598 | Octavia Amb 1.5 TSI 110kW e-TEC DSG MY21 | 11,879 |

| Tax Code | Labour | Material | GST % | GST | Total amount excl. GST | Total amount incl. GST |
|----------|----------|----------|-------|--------|------------------------|------------------------|
| Total | 2,010.00 | 8,574.64 | | 740.92 | 10,584.64 | 11,325.56 |

Customer

Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|---|
| Date of Submission | 24/05/2022 12:43 (SGT) |
| Date of Accident | 23/05/2022 21:30 (SGT) |
| Exact Location of Accident | SG, Beach Rd, Golden Mile Complex, Singapore 199588 |
| Additional Location Information | GOLDEN MILE |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNC6396L

INSURED/POLICYHOLDER

| | |
|--------------------------|----------------------|
| Is company? | No |
| Name Of Registered Owner | ONG BOON LEONG |
| NRIC No | SXXXX644E |
| Email Address | ongblsg@hotmail.com |
| Mobile Phone No | (Phone) +65-91097406 |
| Alternative Phone No | +65-91097406 |

VEHICLE PARTICULARS

| | |
|--|--|
| Manufacturer | Skoda |
| Model | Octavia |
| Variants | Octavia Amb 1.5 TSI 110kW e-TEC DSG MY21 |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1500 |

INSURANCE COMPANY

| | |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA Insurance Pte Ltd |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | - |
| Cover Note Number | - |

DRIVER

| | |
|----------------|----------------|
| Name of Driver | ONG BOON LEONG |
| NRIC No | SXXXX644E |

| |
|-----------------------|
| 09/03/1971 |
| Indoor |
| 10/08/1991 |
| 30 YEARS AND 9 MONTHS |
| Male |
| (Phone) +65-91097406 |
| +65-91097406 |
| ongblsg@hotmail.com |
| BLK 23 SIN MING ROAD |
| #12-07 |
| 570023 |
| Yes |
| - |
| No |
| - |
| - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|-------------------------------|
| Type of Accident | Collision - Change/cross lane |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SMU112X |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private car |
| Name of Driver | GOH SOON TECK |
| NRIC No | SXXXX674E |
| Contact Number | (Phone) +65-91144335 |
| Address | - |

Complement
Insurance Company Name
Amount of Damage
Description of property damaged in accident
Name of Passenger (Including Driver)

-
-
-
-
-

