



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref: CS/ASM22004953/Kvcm4

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

Date: 08/06/2022

ATTN: YVONNE ANG

Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8151J	Veh. Inspected	SLT 7000G
Policy No.		Coverage (\$)	0.00
Claim No.	S2M03XT6	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	26/05/2022

2. Vehicle Particulars & Condition

Make & Model	RENAULT KADJAR (A)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1RFE00355897309	Colour	METALLIC DARK BLUE
Odometer	225705 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R19	CONTINENTAL	3 mm
L/H Front Tyre	225/45 R19	CONTINENTAL	3 mm
R/H Rear Tyre	225/45 R19	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R19	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/04/2022	Inspection Date	26/05/2022
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**