

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	lef:	CS/AGI22004974/Any3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	15/07/2022	
			С	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SDX 646M	Veh. Inspected		SLU 6413A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10015294/JT	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		26/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI ELANTRA	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	KMHD841CMJU591399	Colour		BLUE	
	Odometer	108482 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	CELERITAS		6 mm	
	L/H Front Tyre	205/55 R16	CELERITAS		6 mm	
	R/H Rear Tyre	205/55 R16	CELERITAS		6 mm	
	L/H Rear Tyre	205/55 R16	CELERITAS		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	14/05/2022	Inspection Date		25/05/2022	
	Survey held at NEW ZEN WERKZ PTE LTD					
		3 KAKI BUKIT ROAD 1, #03-04, SINGAPORE 415935				
5a.	Sa. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: