

ASS. REC. BY:

REF:

072/220049911K+

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop r/vs

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

GBF 23646

Yr Regn:

08, 1.6

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV350

c.c

2488

Colour

M. D. Brown

Sp. Reading

119937

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNIMC 242680006639

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195R15X8

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

24/3/22

D.O.I.

27/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WENG SENG HENG CHINESE MEDICAL HALL
221 HENDERSON RD
#07-15
SINGAPORE 159557

TEL: 62782070
ATTN:

Estimate No: MC1902703
Date: 26 May 2022
Policy No: D21MTPCVE002051
Veh Reg No: GBF2364G
Make/Model: NISSAN NV350 PANEL VAN 2.5

Your Ref No: GBF2364G
Claim Type: Third Party → China
Accident Date: 24/05/2022
TP Veh Reg No: SMX8443Y

*Not Withheld
11 Days @
Repair After Paint 6 days*

Estimate Repair Cost to Vehicle No :GBF2364G

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 TAILGATE	1 PC	2,100.00	✓
2 TAILGATE EMBLEM	1 PC	78.00	✓
3 TAILGATE NV350 LOGO	1 PC	110.00	✓
4 TAILGATE URVAN LOGO	1 PC	64.90	✓
5 TAILGATE LOCK	1 PC	330.00	X
6 TAILGATE INNER TRIM CLIPS	16 PC	88.00	X
7 TAILGATE RUBBER	1 PC	155.00	?
8 TAILAMP RH	1 PC	255.00	✓
9 TAILAMP GROMMET TOP	1 PC	5.50	X
10 TAILAMP GROMMET BTM	1 PC	5.50	X
11 REAR BUMPER	1 PC	667.00	✓
12 REAR BUMPER SIDE RETAINER RH	4 PC	56.00	✓
13 REAR BUMPER CLIPS	7 PC	38.50	✓
14 REAR BUMPER GROMMET	3 PC	16.50	X
15 REAR STEP PANEL	1 PC	210.00	X
16 REAR END PANEL OUTER	1 PC	217.00	?
17 REAR END PANEL INNER	1 PC	576.00	✓
18 REAR FENDER OUTER RH	1 PC	2,300.00	?
19 REAR FENDER INNER TRIM CLIPS	17 PC	93.50	X
20 REAR AIR VENT	1 PC	76.00	?
		7,442.40	
	Less 10%	744.24	6,698.16
Special Nett			
21 INNER SEAL	1 PC	20.00	✓
22 WINDSCREEN SEALANT	1 PC	40.00	✓
23 TAILGATE STICKER 8 PAX	1 PC	10.00	✓
24 TAILGATE STICKER 70KM/H	1 PC	10.00	✓
25 TAILGATE STICKER COMPANY NAME - CHECK PRICE	1 PC	0.00	✓
26 TAILGATE STICKER MASCOT - CHECK PRICE	1 PC	0.00	?
27 REVERSE SENSOR	1 SET	200.00	✓
28 REAR FENDER STICKER RH - CHECK PRICE	1 PC	0.00	?
		280.00	280.00

LABOUR

29 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.

1 PC 40.00

201

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : WENG SENG HENG CHINESE MEDICAL HALL
221 HENDERSON RD
#07-15

SINGAPORE 159557

TEL: 62782070

ATTN:

Your Ref No: GBF2364G

Claim Type: Third Party

Accident Date: 24/05/2022

TP Veh Reg No: SMX8443Y

SURVEYOR COPY

Estimate No: MC1902703

Date: 26 May 2022

Policy No: D21MTPCVE002051

Veh Reg No: GBF2364G

Make/Model: NISSAN NV350 PANEL
VAN 2.5

Estimate Repair Cost to Vehicle No :GBF2364G

Description	Quantity	List Price	Amount
30 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	S\$ 120.00	S\$ ✓
31 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	80.00	7
32 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
33 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	501
34 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL,REAR OUTER FENDER RH. TO KNOCK & REPAIR REAR FLOOR PANEL,REAR INNER FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	7501
35 TO SPRAY TAILGATE,REAR END PANEL,REAR FENDER RH,REAR FLOOR PANEL.	1 PC	1,000.00	8001
		2,360.00	2,360.00
		Total	S\$ 9,338.16
		Add GST @ 7%	653.67
		Total Amount Payable	S\$ 9,991.83

TOTAL: SINGAPORE DOLLAR NINE THOUSAND NINE HUNDRED NINETY ONE AND CENTS EIGHTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ah Lim Company
AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/05/2022 11:37 (SGT)
Date of Accident 24/05/2022 10:40 (SGT)
Exact Location of Accident Jln Toa Payoh, Singapore
Additional Location Information SLIP RD OF TPY TO PIE TWDS CHANGI
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF2364G
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner WENG SENG HENG CHINESE MEDICAL HALL PTE LTD
Company Reg No 1XXXXX280G
Email Address WENGSENGHENG@SINGNET.COM.SG
Mobile Phone No (Phone) +65-98515253
Alternative Phone No (Office) +65-62782070

VEHICLE PARTICULARS

Manufacturer Nissan
Model Nv350
Variant NV350 PANEL VAN 2.5 5AT 5DR EURO V
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Auto
CC 2488

INSURANCE COMPANY


Name of Insurance Company Sompo Insurance Singapore Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number D21MTPCVE002051
Cover Note Number 08/08/2021 - 07/08/2022

DRIVER

Name of Driver CHUA CHIT HENG
NRIC No SXXXX981Z

Date of accident: 24/05/22 Time: 10:40am Location: Slip Road of Tea Potok leading to PIE
 My Vehicle A: GBF 2364G Vehicle B: SMX 8443Y Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 24/05/2022 at about 10:40am I was approaching the slip
 Road of Tea Potok leading to PIE towards Changi - I was
 stationary when suddenly I felt a strong impact on the
 rear and realise that SMX 8443Y could not stop in time
 and hit onto my van's rear.

☐ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I hereby declare that the particulars are true in every respect.

WENG SENG HENG CHINESE MEDICAL HALL PTE. LTD.

221 HENDERSON ROAD

#07-15 HENDERSON BUILDING

SINGAPORE-159557

Policyholder's Signature (4 LINES)

Date & Time: FAX: 6270 4123

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Ah Lim Motor Company

Reporting Centre Personnel's Signature

Name:

NRIC/FIN:

COMPLETED 2 MAY 2022