

REFERENCES

SMK6377L Yr Regn: 2019, April.

Veh No: SMR601/L Yr Regn: 2011/11/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis. C.C 1598

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading 44761 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 1N2053KEH 60459 6178

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17.

R: 215/45247.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or

Front Rear

R/Bal.	06	mm	R/Bal.	06	mm
--------	----	----	--------	----	----

L/Bal.	06	mm	L/Bal.	06	mm
--------	----	----	--------	----	----

DOA D.O.I. 97/05/22

Survey held at Jack Cars.

Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China.
	MV :
	PV :
	Nett :
	885Z .

☐: Preli. Report

☐: Final Report

Days Of Repair: .

Resurvey No. of Trip:

Add Fee: : Site Insp (\$☐ : Site Insp (\$

□ Interview (\$

Tech. Invs (3)

Transportation:

$$S + RS, \quad S$$

Pholcus

Others: