ASS. Filed By: GQ | REF: CS/AIS22005007/Gqy3

ASSIGNMENT

From: Date:

Estimated Cost:

[OD] / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s VIN'S MOTOR

of

Insured:

Policy No.

Claims No. 2022 22004996FR

Sum Insured: Excess: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $86k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / [REV] / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKE5461M Yr Regn: 13 Mar 2012

Type [M.Car] M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ C 180 c.c 1597

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 105833 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2040452A679929 *

Gen. Cond [Good] / Fair / Poor / Burnt

Steering: [norder] / Jammed / Leaked / Burnt or

Brake: [norder] / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / S[TD A/R]m or

Tyre Size: F: 225/45ZR17

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / [MIC] / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	27-05-2022

Survey held at W/S 11:30

Des. of Damages : [Frt] / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/05/22@12.26pm revert to AIS by email.	
30/05/22@6.23pm Faiz informed C/A on part by part basis & ex:$1100 by email.	
31/05/22@9.16am Informed Raymond C/A on part by part basis & ex:$1100 by email.	

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

[ ] : Preli. Report

[ ] : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($)

[ ] : Interview ($)

[ ] : Tech. Invs ($)

[ ] : Weekend ($)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL