



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |  |                    |
|--|---|--|--------------------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |   | Ref: CS/AGI22005039/Vny3m4<br>Date: 22/08/2022 | Code: AGI          |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |  |                    |
| Insured Veh.   | SJN 3890K   | Veh. Inspected                                 | SMR 6754U          |
| Policy No.   |   | Coverage (\$)                                  | 0.00               |
| Claim No.  | C10015458/CD  | Excess (\$)                                    | 0.00               |
| Assign From  | MAYBIE CHUA   | Assign Date                                    | 27/05/2022         |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |  |                    |
| Make & Model   | TOYOTA VOXY   | c.c  | 1797               |
| Engine No.   | HIDDEN  | Year of Reg.                                   | 2020               |
| Chassis No.  | ZWR800416931  | Colour   | BLACK              |
| Odometer   | 239679 KM   | Steering                                       | IN ORDER           |
| Brakes   | IN ORDER  | Modification                                   | STANDARD ALLOY RIM |
| General  | GOOD  |  |                    |
| <b>3. Conditions of Tyres</b>  |   |  |                    |
|  | Size  | Make   | Balance            |
| R/H Front Tyre   | 195/65 R15  | FARROAD  | 6 mm               |
| L/H Front Tyre   | 195/65 R15  | FARROAD  | 6 mm               |
| R/H Rear Tyre  | 195/65 R15  | FARROAD  | 6 mm               |
| L/H Rear Tyre  | 195/65 R15  | FARROAD  | 6 mm               |
| <b>4. Description of Damages</b>   |   |  |                    |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |  |                    |
| <b>5. General Information</b>  |   |  |                    |
| Accident Date  | 26/05/2022  | Inspection Date                                | 30/05/2022         |
| Survey held at   | N-51 AUTOMOTIVE PL<br>2 KAKI BUKIT AVE 2<br>#01-17 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |  |                    |
| <b>5a. Remarks</b>   |   |  |                    |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |   |  |                    |
| <b>5b. Estimate Days of Repair</b>   |   |  |                    |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 6 Working Days                                 |                    |