



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI18021506/Rqy3e2-1	
			Date: 04/10/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBC 5045Z	Veh. Inspected	FBN 711J	
Policy No.	DMCVSN3052561800	Coverage (\$)	0.00	
Claim No.	SNM18D05163C02	Excess (\$)	0.00	
Assign From	Brij Rai / Ambrose Lee	Assign Date	28/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CB190X	c.c	184	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	LWBPCL1AXH1005376	Colour	MULTI COLOUR	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	110/70 R17	RADIAL	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	RADIAL	4 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/10/2018	Inspection Date	28/11/2018	
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	