


### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SHB 127M  
 at Workshop m/s STRINGS (SMPT)  
 of 60, Woodmans Ind PK E4  
 Insured: CTI  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 127M Yr Regn: 2021 / SH  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: MG MG5 EV EXCITE T c.c. \_\_\_\_\_  
 Colour: GREEN A/C: Insured / Std / NI / NA  
 Sp. Reading: 61401 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: LS 3E2403XMG051387  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modl: NII / SRim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or WESTLAK  
 Front: R/Bal. 6 mm L/Bal. 6 mm  
 Rear: R/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 25/05/22 D.O.I. 26/05/22  
 Survey held at STRINGS  
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time, File Return to?  
 Report Formed: \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_ \$ + RS. \_\_\_\_\_ \$  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)

# Case Details

Case Reference Number :  
TAX/05/22/2072  
Type of Repair : Accident Repair  
Vehicle Registration Number :  
SHB127M

Company Type : Strides Taxi Pte Ltd  
Estimation ID : EST-18378-ID  
Assigned By : Taxi Claims Manager  
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd  
Accident Date and Time : 25/05/2022 01:30 AM  
Vehicle Age(In Months) : -

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
Standard	Main			FASCIA-FRT BPR	1	721.66	721.66	10.00	649.49	Replace	0	0	Not Give	Xm
Standard	Main			FINISHER-FRT BPR - LH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Give	Xm
Standard	Main			FINISHER-FRT BPR - RH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Give	Xm
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	Xm
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	Xm
Standard	Main			GRILLE ASM-RAD	1	978.02	978.02	10.00	880.22	Replace	1	880.22	Replace	OK
Standard	Main			INSERT-FRT LIC PLT EMB	1	30.26	30.26	10.00	27.23	Replace	1	27.23	Replace	OK
Standard	Main			BAR ASM-FRT BPR IMP	1	624.00	624.00	10.00	561.60	Replace	0	0	Not Give	Xm
Standard	Main			SOCKET-CHRG	1	2,036.74	2,036.74	10.00	1,833.07	Replace	0	0	Check	?
Total Spare Part Cost									4,189.45	Surveyor Total		907.45		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									4,189.45	Final Sur Total		907.45		

### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,200.00	200	
Total:			1,200.00	200.00	

**Cost Detail**

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	0	XM
<b>Total:</b>			<b>428.00</b>	<b>0.00</b>	

**Other Cost Detail**


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	XM
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	XM
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	XM
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	XM
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	XM
6	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
7	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
<b>Total:</b>			<b>1,080.00</b>	<b>300.00</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,189.45	907.45
Total Labour Cost	1,200.00	200.00
Total Spray Painting	428.00	0.00
Other	1,080.00	300.00
<b>Overall Total</b>	<b>6,897.45</b>	<b>1,407.45</b>
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	1,407.45
Surveyor Approved Amount		1,407.45
No of Repair Days*	5	2
Remarks		PART BY PART REPAIR / RESURVEY NEW AND OLD PARTS PHOTO . REQUIRED DISMANTLING PHOTOS OF THE FRONT
Surveyor Name		Rasul

Estimator Assessment(\$)

Surveyor Assessment(\$)



Save

Clear

Survey Date

26/05/2022

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(27)

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	25/05/2022 16:18 (SGT)
Date of Accident	25/05/2022 09:30 (SGT)
Exact Location of Accident	E Coast Park Service Rd, East Coast Park, Singapore
Additional Location Information	EAST COAST PARK SERVICE ROAD TOWARDS MARINE PARADE ROAD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB127M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-6866272

### VEHICLE PARTICULARS

Manufacturer	MG
Model	MG5
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1

### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

### DRIVER

Name of Driver	YUSRIE BIN SHARIP
----------------	-------------------

NRIC No	SXXXX583B
Date Of Birth	18/08/1972
Occupation	Outdoor
Date Of Driving Pass	25/08/2004
Driving experience	17 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662671
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	RELIEF
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS STATIONARY ALONG THE SLIP ROAD OF EAST COAST SERVICE ROAD TOWARDS MARINE ROAD AS I WAS WAITING FOR THE FRONT LORRY YP7302C TO MOVE. SUDDENLY THE VEHICLE REVERSED AND HIT ONTO THE FRONT PORTION OF MY TAXI. I WAS NOT ABLE TO COMMUNICATE WITH THE LORRY DRIVER, AS SUCH I SPOKE TO THE BOSS OVER THE PHONE. HE WANTED A PRIVATE SETTLEMENT BUT I DECIDED TO REPORT TO THE COMPANY AS REQUESTED BY MY HIRER.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP7302C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

Commercial vehicle

-  
-  
-  
-  
-  
-  
-  
-

o  
tik  
Rep  
epo.



SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report **correctly** the details of the accident to speed up the claims process.
- 2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
- 3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. **Any false reporting may be referred to the Police for investigation**
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes



Policyholder's Signature / Date & Time

Sketch Plan

*Rafiah*

25 MAY 22

*Lin 25.5.2022*

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB127M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2022
Vehicle Make:	M.G.
Vehicle Model:	MG5 EV EXCITE T
Primary Colour:	Green
Manufacturing Year:	2021
Engine No.:	-
Chassis No.:	LSJE2403XMG051387
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$29,058.00
Original Registration Date:	23 Sep 2021
First Registration Date:	23 Sep 2021
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2029
PARF Rebate Amount:	\$3,750.00

COE Expiry Date:	22 Sep 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,364.00
COE Rebate Amount:	\$34,159.00
Total Rebate Amount:	\$37,909.00

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 May 2022

OK