

Section A - Accident Details

Registration Number	SHB127M
Case Reference Number	TAX/05/22/2072
Registration Date	23/9/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	YUSRIE BIN SHARIP
Type of Accident	Others
Accident Date and Time	25/5/2022 9:30 AM
Accident Reported Date and Time	25/5/2022 2:06 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115091
Special Instruction to ARC,if any	TP/Front PORTION
Prepared Date and Time	25/5/2022 3:58 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$200.00
Total Spray Cost	\$428.00	\$0.00
Total Spare Part Cost	\$4,189.45	\$907.45
Total Other Cost	\$1,080.00	\$300.00
TOTAL COST	\$6,897.45	\$1,407.45 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / China Taiping
ARC / Surveyor Sign Off Date	25/05/2022 4:07 PM	26/05/2022 2:49 PM
Signature		
Remarks		PART BY PART REPAIR / RESURVEY NEW AND OLD PARTS PHOTO . REQUIRED DISMANTLING PHOTOS OF THE FRONT BUMPER .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2206-0116	Invoice Number	
Quotation Date	10.06.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,200.00	\$200.00 ✓
Total Labour	\$1,200.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$428.00	\$0.00
Total Spray Painting & Panel Beating	\$428.00	\$0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00 ✓
ISOLATED OF (EV) (NET)	\$150.00	\$150.00 ✓
Total Other Costs	\$1,080.00	\$300.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10361096	FINISHER-FRT BPR - RH	0.00	\$98.80	0.00	\$0.00	Replace	Not Given
		10325882-SPRP	FASCIA-FRT BPR	0.00	\$721.66	0.00	\$0.00	Replace	Not Given
		10361095	FINISHER-FRT BPR - LH	0.00	\$98.80	0.00	\$0.00	Replace	Not Given
		11171352-SEPP	BAR ASM-FRT BPR IMP	0.00	\$624.00	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given
		10751478	GRILLE ASM-RAD	1.00	\$978.02	10.00	\$880.22	Replace	Replace
		10251535	INSERT-FRT LIC PLT EMB	1.00	\$30.26	10.00	\$27.23	Replace	Replace
		11011337	SOCKET-CHRG	0.00	\$2,036.74	0.00	\$0.00	Replace	Check
Total					\$4,648.28		\$907.45		

X } NN
✓ Cra
✓ Nec
X NN

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

907.45
+ 200.00
+ 300.00
1,407.45