

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5TW 6186 Yr Regn: 10/2/20

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vario c.c. 149Colour: White A/C: Insured / Std / NI / NASp. Reading: 4161 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMKKF3770K13 015/40

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/80-14R: 100/80-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. mm L/Bal. mm

D.O.A. 20/5/99 Sathern Motor D.O.A. 20/5/99

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NIV #17000</u>
	<u>RN 7000 - \$2300.99</u>

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.E. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL



南方摩哆 Southern Motor

Business Reg. No: 234147/001.

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

30 May 2022

Lonpac Insurance Bhd

300 Beach Road #17-04/07

The Concourse

Singapore (199555)

Dear Sirs,

RE: Cost of repair to Honda Var10 -JTW6186

1set of Front Fork Comp	?	S\$	280.00
1pc of Head Lamp Comp	/ mis		380.00
1pc of Front Body Set	/ cut		480.00
1pc of Meter Cover	/ mis		180.00
1pc of Handle Bar	/ Ji		110.00
1pc of Brake Cable	/ cut		85.00
1pc of Front Lamp Stay Bracket	/ Ji		65.00
1pc of Exhaust Pipe Cover	/ cut		65.00
1pc of Handle Balancer	/ cut		45.00
1pc of Givi Box	/ cut		120.00
			1,810.00
		Less 10%	181.00
		Nett	1,629.00
		Transport	30.00 /
		Jack & Alignment Body	380.00 150
		Labour	300.00 200
			<u>\$2,339.00</u>

Yours Faithfully,
Southern Motor



Steve (LKK)

31/5/22, 12.00pm

8322 8813

ML
L/S
M/L/G
3 L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SINGAPORE POLICE FORCE



T/20220520/2086

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No: T/20220520/2086

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/05/2022 17:55	Vide Report No.: J/20220520/0080	Station Diary No.: 115
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: FOO OI KHOON			Address:		
ID Type / ID No.: FIN NO / G7044054M			Contact No.: Home/Office: Mobile: 81361862		
Nationality: MALAYSIAN			Email:		
Sex: Female	Age: 46	Date of Birth: 21/05/1975	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: MACHINE OPERATOR			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury: Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 20/05/2022 15:10	Type of Location: Straight Road
Location: GUL WAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JTW6186	Motorcycle	HONDA		Grey	Totally Damaged	0
YM6501S	Lorry			White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20220520/2086

2 of 3

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20220520/2086

CONTINUATION OF REPORT

Rider		ID No.		G7044054M	
Name	FOO OI KHOON			Contact No.	81361862
Related Vehicle	JTW6186 (Motorcycle)			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Hospital/Clinic	NIL			Date Treatment	NIL
No. of Days granted Medical Leave			NIL	Date Discharge	NIL
Degree of Injury			Slight		
Driver		ID No.		S1180162E	
Name	SANUSI BIN ARSRIP			Contact No.	85699632
Related Vehicle	YM6501S (Lorry)			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Hospital/Clinic	NIL			Date Treatment	NIL
No. of Days granted Medical Leave			NIL	Date Discharge	NIL
Degree of Injury			NIL		


Brief Details.

On 20.05.2022 at about 1510hrs, I was riding my motorcycle; JTW6186 along Gul Way heading towards Pioneer Road. However along the way, a lorry; YM6501S from the opposite lane turned into no. 20 Gul Way. I tried to avoid a collision by maneuvering to the right however do not wish to travel onto opposite lane as I fear for more oncoming traffic. I side swipe the rear of the said lorry and subsequently fell from my motorcycle.

After the incident, the driver of the lorry came down from his vehicle and we exchanged particulars. My colleagues witness the incident and called for both the police and ambulance vide; J/20220520/0080. I sustained minor abrasions and scratches on both my arms, right leg and rear torso.

I was advised to make a police report on the matter.

**SINGAPORE
POLICE FORCE**



T/20220520/2086

1 of 1

Report No. T/20220520/2086

Station Of Origin:
West N.P.C
Corporation Road SINGAPORE 649818
No: 1800-2689999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

STAFF SGT MOHAMMED
AMIRULHAFIZ BIN RAMLAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TR / AET /
SI MOHAMAD ZULFAZOLI BIN ABDULLAH
Contact No: 85476204

Signature Of Informant:

Date/Time:
20/05/2022 17:55

Classification Of Case:



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

FD

No. Pendaftaran : JTW6186
No. ID : 750521055238
Nama Pemunya Berdaftar : FOD 01 KH00N
Alamat : NO 47 JLN NUSA PERINTIS 9/3 TMN NUSA PERINTIS 2
81550 GELANG PATAH JOHOR

No. Chasis/No. Enjin : PMKKE3770KB015740 / KF29E8063674
Buatan/Nama Model : HONDA / VARIO (ACB150CBTK)
Keupayaan Enjin : 149
Bahan Bakar : PETROL
Status Asel : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2020
Tarikh Pendaftaran : 10/02/2020
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -