



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI22005106/Kty3e2 Date: 09/06/2022 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YQ 4882J	Veh. Inspected	SMG 6482L
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004173	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	30/05/2022
2. Vehicle Particulars & Condition			
Make & Model	RENAULT SCENIC (A)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VF1RFA00361665858	Colour	METALLIC RED
Odometer	75582 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R20	TOURADOR	7 mm
L/H Front Tyre	195/55 R20	TOURADOR	7 mm
R/H Rear Tyre	195/55 R20	TOURADOR	7 mm
L/H Rear Tyre	195/55 R20	TOURADOR	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/05/2022	Inspection Date	31/05/2022
Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	