

(08/11/13) wef  
ASS. REC. BY: *[Signature]*

REF: NS/INC22005125/Rvc

369K

### ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SHC 45889*

at Workshop m/s *STRIPES (CENR)*

of *60,000,000 Ind PK KEY*

Insured: *SKV 9065H NTNL*

Policy No.

Claims No. *MT/1176972-001*


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: *SHC 45889* Yr Regn: *2017 / NLC*

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: *TOYOTA PRIUS HYBRID 1.8 CVT c.c 1798*

Colour: *Maroon* A/C: Insured / Std / NI / NA

Sp. Reading: *524312* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *JTDKB3FU103879920*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: *195/65R15*

R: *22*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *SAILUN*

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *28/05/22* D.O.I. *30/05/22*

Survey held at *STRIPES*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*Rear o/s*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/6/22 Rasul informed LS \$1450 (red 9115.50, 86%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: *3*

1)

☐ : Final Report

Resurvey No. of Trip: *1*

Date/Time, File Return to?

Survey Fee:

2) 21/6/22-typist

Add Fee: ☐ : Site Insp (\$

Transportation:

Report Format: TP

Lump Sum / I.B.I: (\$ 1450

☐ : Interview (\$

) S + RS, SI

☐ : Tech. Invs (\$

) Photos

☐ : Weekend (\$

) Others

TOTAL



## Case Details

Case Reference Number :  
TAX/05/22/2077  
Type of Repair : Accident Repair  
Vehicle Registration Number :  
SHC4588J

Company Type : Strides Taxi Pte Ltd  
Estimation ID : EST-18408-ID  
Assigned By : Taxi Claims Manager  
Team

Insurance Company Name : NTUC Income Insurance Co-operative  
Ltd  
Accident Date and Time : 28/05/2022 04:40 AM  
Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation |              |         |                 |                              |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                    | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| Standard            | Main         |         |                 | COVER, RR BUMPER ASSY        | 1   | 423.90                  | 423.90         | 25.00  | 317.92          | Replace         | 1                 | 317.92                   | Replace ▾      | de ✓    |
| Standard            | Main         |         |                 | REAR BUMPER REINFORCEMENT    | 1   | 318.80                  | 318.80         | 25.00  | 239.10          | Replace         | 0                 | 0                        | Check ▾        | ? ✓     |
| Standard            | Main         |         |                 | PAD, RR BUMPER, RH & LH , 1  | 2   | 3.80                    | 7.60           | 25.00  | 5.70            | Replace         | 2                 | 5.70                     | Replace ▾      | nee ✓   |
| Standard            | Main         |         |                 | PAD, RR BUMPER, RH & LH , 2  | 2   | 3.80                    | 7.60           | 25.00  | 5.70            | Replace         | 2                 | 5.70                     | Replace ▾      | nee ✓   |
| Standard            | Main         |         |                 | PAD, RR BUMPER, RH & LH , 3  | 2   | 3.80                    | 7.60           | 25.00  | 5.70            | Replace         | 2                 | 5.70                     | Replace ▾      | nee ✓   |
| Standard            | Main         |         |                 | PAD, RR BUMPER, CTR          | 3   | 2.20                    | 6.60           | 25.00  | 4.95            | Replace         | 3                 | 4.95                     | Replace ▾      | nee ✓   |
| Standard            | Main         |         |                 | SEAL, RR BUMPER ARM, RH & LH | 2   | 11.00                   | 22.00          | 25.00  | 16.50           | Replace         | 2                 | 16.50                    | Replace ▾      | nee ✓   |
| Standard            | Main         |         |                 | STOPPER, RR BUMPER, RH & LH  | 2   | 4.30                    | 8.60           | 25.00  | 6.45            | Replace         | 0                 | 0                        | Not Give ▾     | nee Xm  |
| Standard            | Main         |         |                 | RETAINER, RR BUMPER, RH      | 1   | 112.70                  | 112.70         | 25.00  | 84.53           | Replace         | 0                 | 0                        | Not Give ▾     | nee Xm  |
| Standard            | Main         |         |                 | RETAINER, RR BUMPER, LH      | 1   | 111.50                  | 111.50         | 25.00  | 83.63           | Replace         | 0                 | 0                        | Not Give ▾     | nee Xm  |
| Standard            | Main         |         |                 | SEAL, RR BUMPER , RH         | 1   | 85.20                   | 85.20          | 25.00  | 63.90           | Replace         | 0                 | 0                        | Not Give ▾     | Xm      |
| Standard            | Main         |         |                 | SEAL, RR BUMPER , LH         | 1   | 85.20                   | 85.20          | 25.00  | 63.90           | Replace         | 0                 | 0                        | Not Give ▾     | Xm      |
| Standard            | Main         |         |                 | CLIPS PIECE, FRT & RR BUMPER | 10  | 1.50                    | 15.00          | 25.00  | 11.25           | Replace         | 10                | 11.25                    | Replace ▾      | nee ✓   |

Total Spare Part Cost 6,476.81

Surveyor Total 940.10

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,803.57

Final Sur Total 752.08

| SMRT Recommendation   |                 |         |                    |                                                            |     |                                  |                   |        |                    |                    | Surveyor Approval    |                                |                |   | Remarks |
|-----------------------|-----------------|---------|--------------------|------------------------------------------------------------|-----|----------------------------------|-------------------|--------|--------------------|--------------------|----------------------|--------------------------------|----------------|---|---------|
| A<br>pe               | Costing<br>Type | Portion | Material<br>Number | Part Name                                                  | Qty | List<br>Price<br>Per<br>Unit(\$) | List<br>Price(\$) | Dis(%) | Final<br>Price(\$) | Repair/<br>Replace | Surveyor<br>Quantity | Surveyor<br>Final<br>Price(\$) | Repair/Replace |   |         |
|                       | Standard        | Main    |                    | GUARD, RR<br>BUMPER, LOWER                                 | 1   | 558.30                           | 558.30            | 25.00  | 418.72             | Replace            | 1                    | 418.72                         | Replace        | ✓ | de ✓    |
|                       | Standard        | Main    |                    | COVER, GUARD<br>RR BUMPER<br>LOWER                         | 1   | 14.80                            | 14.80             | 25.00  | 11.10              | Replace            | 1                    | 11.10                          | Replace        | ✓ | de ✓    |
|                       | Standard        | Main    |                    | SENSOR<br>REVERSE                                          | 1   | 180.00                           | 180.00            | 0.00   | 180.00             | Replace            | 0                    | 0                              | Check          | ✓ | ?       |
|                       | Standard        | Main    |                    | ANTENNA,<br>ELECTRICAL KEY                                 | 1   | 60.30                            | 60.30             | 10.00  | 54.27              | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | REAR BUMPER<br>GROMMET<br>SCREW                            | 2   | 2.20                             | 4.40              | 25.00  | 3.30               | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | LENS & BODY,<br>REAR<br>COMBINATION<br>LAMP , RH           | 1   | 438.10                           | 438.10            | 10.00  | 394.29             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | LENS & BODY,<br>REAR<br>COMBINATION<br>LAMP , LH           | 1   | 438.10                           | 438.10            | 10.00  | 394.29             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | LENS & BODY<br>ASSY , RR<br>BUMPER , RH                    | 1   | 486.80                           | 486.80            | 10.00  | 438.12             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | LENS & BODY<br>ASSY , RR<br>BUMPER , LH                    | 1   | 486.80                           | 486.80            | 10.00  | 438.12             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | COVER, REAR<br>FLOOR UNDER ,<br>RH                         | 1   | 169.50                           | 169.50            | 25.00  | 127.13             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | COVER, REAR<br>FLOOR UNDER ,<br>LH                         | 1   | 234.30                           | 234.30            | 25.00  | 175.73             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | COVER, REAR<br>FLOOR UNDER<br>CENTER                       | 1   | 222.60                           | 222.60            | 25.00  | 166.95             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | TAIL GATE PANEL<br>SUB-ASSY, BACK<br>DOOR                  | 1   | 929.60                           | 929.60            | 25.00  | 697.20             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | TAIL GATE<br>WEATHERSTRIP,<br>BACK DOOR                    | 1   | 360.70                           | 360.70            | 25.00  | 270.53             | Replace            | 0                    | 0                              | Not Give       | ✓ | Xm      |
|                       | Standard        | Main    |                    | TAIL GATE BACK<br>DOOR OUTSIDE<br>GARNISH SUB-<br>ASSY     | 1   | 891.20                           | 891.20            | 25.00  | 668.40             | Replace            | 1                    | 0                              | Repair         | ✓ | R       |
|                       | Standard        | Main    |                    | NAME PLATE<br>(HYBRID) ,<br>LUGGAGE<br>COMPARTMENT<br>DOOR | 1   | 52.30                            | 52.30             | 25.00  | 39.22              | Replace            | 1                    | 39.22                          | Replace        | ✓ | de ✓    |
|                       | Standard        | Main    |                    | NAME PLATE<br>(PRIUS) ,<br>LUGGAGE<br>COMPARTMENT<br>DOOR  | 1   | 52.30                            | 52.30             | 25.00  | 39.22              | Replace            | 1                    | 39.22                          | Replace        | ✓ | de ✓    |
|                       | Standard        | Main    |                    | TAIL GATE LOCK<br>ASSY, BACK<br>DOOR                       | 1   | 452.10                           | 452.10            | 10.00  | 406.89             | Replace            | 0                    | 0                              | Not Give       | ✓ | de Xm   |
| Total Spare Part Cost |                 |         |                    |                                                            |     |                                  |                   |        | 6,476.81           | Surveyor Total     |                      | 940.10                         |                |   |         |
| Lump Sum Discount (%) |                 |         |                    |                                                            |     |                                  |                   |        | 20.00              | Lump Sum Dis (%)   |                      | 20                             |                |   |         |
| Final Spare Part Cost |                 |         |                    |                                                            |     |                                  |                   |        | 4,803.57           | Final Sur Total    |                      | 752.08                         |                |   |         |

T/Radio: Insured / Std / Nv.

WAB

Colour

## SMRT Recommendation

## Surveyor Approval

| JM<br>Type            | Costing<br>Type | Portion | Material<br>Number | Part Name                                     | Qty | List<br>Price<br>Per<br>Unit(\$) | List<br>Price(\$) | Dis(%) | Final<br>Price(\$) | Repair/<br>Replace     | Surveyor<br>Quantity | Surveyor<br>Final<br>Price(\$) | Repair/Replace | Remarks |
|-----------------------|-----------------|---------|--------------------|-----------------------------------------------|-----|----------------------------------|-------------------|--------|--------------------|------------------------|----------------------|--------------------------------|----------------|---------|
| Standard              | Main            |         |                    | TAIL GATE LOCK<br>COVER, BACK<br>DOOR         | 1   | 25.30                            | 25.30             | 25.00  | 18.98              | Replace                | 0                    | 0                              | Not Give       | Xan     |
| Standard              | Main            |         |                    | EMBLEM SUB-<br>ASSY REAR                      | 1   | 46.30                            | 46.30             | 25.00  | 34.72              | Replace                | 1                    | 34.72                          | Replace        | new     |
| Standard              | Main            |         |                    | STRIDES LOGO                                  | 1   | 7.80                             | 7.80              | 0.00   | 7.80               | Replace                | 1                    | 7.80                           | Replace        | new     |
| Standard              | Main            |         |                    | STICKER DECAL<br>6555 8888                    | 1   | 21.60                            | 21.60             | 0.00   | 21.60              | Replace                | 1                    | 21.60                          | Replace        | new     |
| Standard              | Main            |         |                    | TAIL GATE BACK<br>DOOR HINGE<br>ASSY, RH & LH | 2   | 59.10                            | 118.20            | 25.00  | 88.65              | Replace                | 0                    | 0                              | Not Give       | Xan     |
| Standard              | Main            |         |                    | END PANEL SUB-<br>ASSY, BODY<br>LOWER BACK    | 1   | 629.80                           | 629.80            | 25.00  | 472.35             | Replace                | 0                    | 0                              | Not Give       | Xan     |
| Total Spare Part Cost |                 |         |                    |                                               |     |                                  |                   |        | 6,476.81           | Surveyor Total 940.10  |                      |                                |                |         |
| Lump Sum Discount (%) |                 |         |                    |                                               |     |                                  |                   |        | 20.00              | Lump Sum Dis (%) 20    |                      |                                |                |         |
| Final Spare Part Cost |                 |         |                    |                                               |     |                                  |                   |        | 4,803.57           | Final Sur Total 752.08 |                      |                                |                |         |

## Labour's Cost Detail

| S.No.  | Costing Type | Job Scope              | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|------------------------|----------------------------|----------------------------|---------|
| 1      | Main         | TO REPAIR REAR PORTION | 676.00                     | 300                        |         |
| Total: |              |                        | 676.00                     | 300.00                     |         |

## Spray Cost Detail

| S.No.  | Costing Type | Job Scope                              | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|----------------------------------------|----------------------------|----------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER                 | 378.00                     | 200                        |         |
| 2      | Main         | TO RESPRAY TAIL GATE                   | 378.00                     | 0                          | Xan     |
| 3      | Main         | TO RESPRAY TAILGATE OUTSIDE<br>GARNISH | 180.00                     | 100                        |         |
| 4      | Main         | TO RESPRAY REAR PANEL                  | 180.00                     | 0                          | Xan     |
| 5      | Main         | TO RESPRAY BUMPER BEAM                 | 180.00                     | 0                          | Xan     |
| Total: |              |                                        | 1,296.00                   | 300.00                     |         |

## Other Cost Detail

| S.No.  | Costing Type | Job Scope          | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|--------------------|----------------------------|----------------------------|---------|
| 1      | Main         | TO WASH AND VACUUM | 60.00                      | 0                          | Xan     |
| Total: |              |                    | 500.00                     | 40.00                      |         |

| Costing Type  | Job Scope                               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|-----------------------------------------|-------------------------|-------------------------|---------|
| 2 Main        | TO CHECK WIRING AND SYSTEM FUNCTION     | 120.00                  | 0 XM                    |         |
| 3 Main        | TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00                  | 0 XM                    |         |
| 4 Main        | TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00                  | 40                      |         |
| 5 Main        | TO REPLACE SUNDRY PARTS                 | 100.00                  | 0 XM                    |         |
| <b>Total:</b> |                                         | <b>500.00</b>           | <b>40.00</b>            |         |

## Summary

|                          | Estimator Assesment(\$)  | Surveyor Assesment(\$)                        |
|--------------------------|--------------------------|-----------------------------------------------|
| Total Spare Part Detail  | 4,803.57                 | 752.08                                        |
| Total Labour Cost        | 676.00                   | 300.00                                        |
| Total Spray Painting     | 1,296.00                 | 300.00                                        |
| Other                    | 500.00                   | 40.00                                         |
| Overall Total            | 7,275.57                 | 1,392.08                                      |
| Lump Sum Repair Option   | <input type="checkbox"/> | <input checked="" type="checkbox"/>           |
| Lump Sum Total           | 7,300.00                 | 1,400.00                                      |
| Surveyor Approved Amount |                          | 1,400.00                                      |
| No of Repair Days*       | 5                        | 3                                             |
| Remarks                  |                          | LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO. |

Surveyor Name

Rasul

Signature

Save

Clear

Survey Date

30/05/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                         |
|---------------------------------|-------------------------|
| Date of Submission              | 30/05/2022 14:43 (SGT)  |
| Date of Accident                | 28/05/2022 12:40 (SGT)  |
| Exact Location of Accident      | Sembawang Rd, Singapore |
| Additional Location Information | SEMBAWANG ROAD          |
| Country/State of Loss           | Singapore               |

### DETAILS OF OWN VEHICLE

|                             |                            |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SHC4588J                   |
| INSURED/POLICYHOLDER        |                            |
| Is company?                 | Yes                        |
| Name Of Registered Owner    | Strides Taxi Pte Ltd       |
| Company Reg No              | 1XXXXX369K                 |
| Email Address               | AUTO-SVCS-TARC@SMRT.COM.SG |
| Mobile Phone No             | (Phone) +65-68662671       |
| Alternative Phone No        | (Office) +65-68662672      |

### VEHICLE PARTICULARS

|                                                                              |                           |
|------------------------------------------------------------------------------|---------------------------|
| Manufacturer                                                                 | Toyota                    |
| Model                                                                        | Prius                     |
| Variant                                                                      | -                         |
| Exact purpose for which vehicle was being used at time of accident           | -                         |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category                                                             | Taxi                      |
| Transmission                                                                 | Auto                      |
| CC                                                                           | 1800                      |

### INSURANCE COMPANY

|                           |                                |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS First Capital Insurance Ltd |
| Type of Coverage          | ThirdParty                     |
| Fleet Policy              | Yes                            |
| Policy Number             | D-22099115MFSH                 |
| Cover Note Number         | -                              |

### DRIVER

|                |              |
|----------------|--------------|
| Name of Driver | NG KAH THIAM |
| NRIC No        | SXXXX056H    |

|                                                              |                            |
|--------------------------------------------------------------|----------------------------|
| Date Of Birth                                                | 14/10/1955                 |
| Occupation                                                   | Outdoor                    |
| Date Of Driving Pass                                         | 17/01/1977                 |
| Driving experience                                           | 45 YEARS AND 4 MONTHS      |
| Gender                                                       | Male                       |
| Mobile Number                                                | (Phone) +65-68662672       |
| Alt. Phone Number                                            | -                          |
| Email Address                                                | AUTO-SVCS-TARC@SMRT.COM.SG |
| Address                                                      | 11                         |
| Address complement                                           | -                          |
| Postcode                                                     | -                          |
| Is the driver the policyholder?                              | No                         |
| If No, Relationship of the Driver with the Insured           | Hirer                      |
| Does Driver Own Other Vehicles?                              | No                         |
| Vehicle Registration Number of Other Vehicle Owned by Driver | -                          |
| Insurance Company of Other Vehicle Owned by Driver           | -                          |

#### GENERAL INFORMATION OF THE ACCIDENT

|                    |                          |
|--------------------|--------------------------|
| Type of Accident   | Collision - Head to Rear |
| Weather Conditions | Clear                    |
| Road Surface       | Dry                      |

#### OTHER INFORMATION

|                                                                                                     |     |
|-----------------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in the accident?                                                   | No  |
| Number of vehicles involved in the accident                                                         | 2   |
| Was anybody injured in the Accident?                                                                | Yes |
| Was any injured conveyed to hospital by ambulance?                                                  | No  |
| Was any other vehicle or property damaged?                                                          | Yes |
| Number of Passengers (Including Driver)                                                             | 2   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No  |

#### PASSENGER 1

|        |              |
|--------|--------------|
| Name   | ONG YUN JING |
| Gender | Female       |

#### DETAILS OF POLICE ACTION

|                                           |                                          |
|-------------------------------------------|------------------------------------------|
| Was the accident reported to the police?  | Yes                                      |
| Police Station Name                       | Yishun North Neighbourhood Police Centre |
| Police Station Phone No                   | (Phone) +65-18008529999                  |
| Alt. Police Station Phone No              | (Fax) +65-68522299                       |
| Police Station Address                    | 31 Yishun Central Singapore 768827       |
| Was notice of intended Prosecution given? | No                                       |
| If yes, against whom?                     | -                                        |

#### CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT - T/20220528/2065

#### ATTACHMENT(S)

|                                                   |              |
|---------------------------------------------------|--------------|
| Are accident photos available for attachment?     | Yes          |
| Was there any video captured by Car Camera?       | Yes          |
| Reasons for not uploading a video of the accident | FILE TOO BIG |
| Was there any audio recorded?                     | No           |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SKV9065H |
|-----------------------------|----------|

|                                         |                                |
|-----------------------------------------|--------------------------------|
| Vehicle Manufacturer                    | -                              |
| Vehicle Model                           | -                              |
| Vehicle Variant                         | -                              |
| Vehicle Colour                          | -                              |
| Vehicle Category                        | Private car                    |
| Name of Driver                          | MUHAMMAD SYAIRAZI BIN SULAIMAN |
| Contact Number                          | -                              |
| Address                                 | -                              |
| Address complement                      | -                              |
| Postcode                                | -                              |
| Insurance Company Name                  | -                              |
| Nature Of Damage                        | -                              |
| Details of property damaged in accident | -                              |
| No. Of Passenger (Including Driver)     | -                              |

## INJURED PERSONS DETAILS

### INJURED 1

|                                                     |              |
|-----------------------------------------------------|--------------|
| Name of injured person                              | NG KAH THIAM |
| Gender                                              | Male         |
| Phone No                                            | -            |
| Address                                             | -            |
| Address Complement                                  | -            |
| Post Code                                           | -            |
| Approximate Age Years Old                           | -            |
| Injuries Sustained                                  | -            |
| Injured person in which vehicle?                    | SHC4588J     |
| Were seat belts worn?                               | -            |
| Was this injured conveyed to hospital by ambulance? | No           |

### INJURED 2

|                                                     |              |
|-----------------------------------------------------|--------------|
| Name of injured person                              | ONG YUN JING |
| Gender                                              | Female       |
| Phone No                                            | -            |
| Address                                             | -            |
| Address Complement                                  | -            |
| Post Code                                           | -            |
| Approximate Age Years Old                           | -            |
| Injuries Sustained                                  | -            |
| Injured person in which vehicle?                    | SHC4588J     |
| Were seat belts worn?                               | -            |
| Was this injured conveyed to hospital by ambulance? | No           |

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law vers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law vers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law vers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Skotch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Sembawang Road

Witnessed by Reporting Centre Personnel

30.5.2022



A - SHC 4588 J

B - SKV9065 H





SINGAPORE  
POLICE FORCE



T/20220528 2065

Police Station Of Origin:  
Yishun North N.P.C  
81 Yishun Central SINGAPORE 768827  
Tel No: 1800-9529999

Report No. T/20220528 2065

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/05/2022 15:26  
Video Report No.:  
Station Diary No.: 59

## Informant's Particulars

|                                                   |                                                                   |                            |  |
|---------------------------------------------------|-------------------------------------------------------------------|----------------------------|--|
| Name of Informant:<br>NG KAH THIAM                | Address:<br>APT BLK 752 WOODLANDS CIRCLE #12-532 SINGAPORE 730752 |                            |  |
| ID Type / ID No.:<br>NRIC NO / S1188056H          | Contact No.:<br>Home Office: Mobile: 86999946                     |                            |  |
| Nationality:<br>SINGAPORE CITIZEN                 | Email:                                                            |                            |  |
| Sex: Male<br>Age: 66<br>Date of Birth: 14/10/1955 | Type of Informant:<br>Driver                                      |                            |  |
| Race:<br>Chinese                                  | Language:<br>English                                              | Institution / School Name: |  |
| Occupation:<br>Taxi driver                        | Driving License Information:<br>Class: 2B 2A 2.3                  | Date of Expiry:            |  |

## General Information of the Accident

|                                                              |                                             |                          |                                            |                                     |
|--------------------------------------------------------------|---------------------------------------------|--------------------------|--------------------------------------------|-------------------------------------|
| Type of Accident:                                            | Injury Others                               | Drink Driver:<br>No      | Date/Time of Accident:<br>28/05/2022 12:40 | Type of Location:<br>X-Junction     |
| Location:<br>SEMBAWANG ROAD                                  |                                             |                          |                                            |                                     |
| Weather:<br>Clear                                            | Road Surface:<br>Dry                        | Road Speed Limit:        |                                            |                                     |
| Traffic Flow:<br>Two Way                                     | Traffic Control:<br>Traffic Light - Working | Traffic Volume:<br>Light |                                            |                                     |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear |                                             |                          |                                            | Anyone conveyed by ambulance:<br>No |

## Details of Vehicle Involved

| Vehicle No. | Type | Make   | Model                | Color  | Condition        | No of Passenger |
|-------------|------|--------|----------------------|--------|------------------|-----------------|
| S104588H    | Car  | TOYOTA | PRIUS HYBRID 1.8 CVT | Maroon | Slightly Damaged |                 |
| SK19065H    | Car  |        |                      | White  |                  | 0               |

## Details of Person Involved

|                                 |                                |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No     |                                |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |



**SINGAPORE  
POLICE FORCE**



T/20220522/0005

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 766827  
Tel No: 1800-8529999

Report No. T/20220522/0005

**CONTINUATION OF REPORT**

|                                   |                                |                                        |                                             |
|-----------------------------------|--------------------------------|----------------------------------------|---------------------------------------------|
| <b>Passenger</b>                  |                                |                                        |                                             |
| Name                              | ONG YUN JING                   | ID No.                                 | S8711132F                                   |
| Related vehicle                   | SH04588J (Car)                 | Contact No.                            | 90231332                                    |
| Hospital/Clinic                   | MOUNT ALVERNIA HOSPITAL        | Class of Driving Licence & Expiry Date | Class: N<br>Date of Expiry: NIL             |
| Date Treatment                    | 23/05/2022                     | Date Discharge                         | 28/05/2022                                  |
| No. of Days granted Medical Leave | 05                             | Degree of Injury                       | Slight                                      |
| <b>Driver</b>                     |                                |                                        |                                             |
| Name                              | NG KAH THIAN                   | ID No.                                 | S1183056H                                   |
| Related Vehicle                   | SH04588J (Car)                 | Contact No.                            | 86999948                                    |
| Hospital/Clinic                   | MOUNT ALVERNIA HOSPITAL        | Class of Driving Licence & Expiry Date | Class: 2E, 2A, 2, 3<br>Date of Expiry: NIL  |
| Date Treatment                    | 28/05/2022                     | Date Discharge                         | 28/05/2022                                  |
| No. of Days granted Medical Leave | 05                             | Degree of Injury                       | Slight                                      |
| <b>Driver</b>                     |                                |                                        |                                             |
| Name                              | MUHAMMAD SYAIRAZI BIN SULAIMAN | ID No.                                 | S9334368I                                   |
| Related Vehicle                   | NIL                            | Contact No.                            | 96181470                                    |
| Hospital/Clinic                   | NIL                            | Class of Driving Licence & Expiry Date | Class: 2B, 2A, 2, 3A<br>Date of Expiry: NIL |
| Date Treatment                    | NIL                            | Date Discharge                         | NIL                                         |
| No. of Days granted Medical Leave | NIL                            | Degree of Injury                       | NIL                                         |

**Brief Details.**

On 28/05/2022 at about 1240hrs, I was driving my taxi along Sembawang Road (north bound) and came to a stop at the Junction of Sembawang Road and Yishun Avenue 1 as the traffic light was red. I was not raining and there were not much vehicles. There was a passenger in my taxi. Suddenly, I felt a sudden impact from the rear and I went down to take a look. I then asked the driver for knocking me and he replied that he was trying to take some goods and did not notice. Due to the accident, the rear bumper of my taxi was damaged. The other driver and I then exchanged phone numbers and went on to our separate ways. After which, my passenger and I felt some discomfort and sought medical attention at Mount Alvernia Hospital. The both of us were given 5 days of MC. My passenger's glasses were also broken.

REAR FORCE

REAR FORCE



SINGAPORE  
POLICE FORCE



T/20220525/2085

Police Station Of Origin:  
Marine North M.P.C  
311 Yishun Central SINGAPORE 768827  
Tel No. 1800-6879999

4.072

Report No. T/20220525/2085

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474333 stating the report number as reference.

Signature of Officer Recording The Report:

L7

SGT 2 BENJAMIN TAN CHAO  
FENG

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date Time:  
26/05/2022 15:26

Officer In Charge Of Case:  
TP / AEU /  
SIANG YITING, STEPHANIE  
Contact No. 9376414

Classification Of Case:

NP168

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                               |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Company                              |
| Owner ID:                     | 369K                                 |
| Vehicle No.:                  | SHC458BJ                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 30 May 2022                          |
| Vehicle Make:                 | TOYOTA                               |
| Vehicle Model:                | PRIUS HYBRID 1.8 CVT                 |
| Primary Colour:               | Maroon                               |
| Manufacturing Year:           | 2017                                 |
| Engine No.:                   | 2ZR8289236                           |
| Chassis No.:                  | JTDKB3FU103579920                    |
| Maximum Power Output:         | 90.0 kW (120 bhp)                    |
| Open Market Value:            | \$29,007.00                          |
| Original Registration Date:   | 19 Dec 2017                          |
| First Registration Date:      | 19 Dec 2017                          |
| Transfer Count:               | 0                                    |
| Actual ARF Paid:              | \$5,000.00                           |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 18 Dec 2025                          |
| PARF Rebate Amount:           | \$3,750.00                           |
| COE Expiry Date:              | 18 Dec 2025                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 8                                    |
| PQP Paid:                     | \$34,159.00                          |
| COE Rebate Amount:            | \$15,151.00                          |
| Total Rebate Amount:          | \$18,901.00                          |

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 May 2022

OK