



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22005147/Vny3e2 Date: 02/09/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 7896A	Veh. Inspected	GY 3973H
Policy No.		Coverage (\$)	0.00
Claim No.	C10015477 /JM	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	31/05/2022
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JN1SF4F23Z0853925	Colour	SILVER
Odometer	555468 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	6 mm
L/H Front Tyre	195 R15C	MICHELIN	6 mm
R/H Rear Tyre	195 R15C	MICHELIN	6 mm
L/H Rear Tyre	195 R15C	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/05/2022	Inspection Date	31/05/2022
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	