

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI22005157/Any3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	28/09/2022	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJX 6452U	Veh. Inspected		SKV 9103G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10015474 /KY	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		30/05/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN SCIROCCO	c.c		1390	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WVWZZZ13ZHV003901	Colour		BLUE	
	Odometer	69743 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/40 R18	BRIDGESTONE		6 mm	
	L/H Front Tyre	235/40 R18	BRIDGESTONE		6 mm	
	R/H Rear Tyre	235/40 R18	BRIDGESTONE		6 mm	
	L/H Rear Tyre	235/40 R18	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	26/05/2022	Inspection Date		30/05/2022	
	Survey held at	ADVANCE AUTO GARAGE	•			
		23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
1					_	

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: