

ASS. REQ. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMJ5744D Yr Regn: 2018 / August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 216i C.C. 1499

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 71941 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA2D920705 LS 3320

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18

R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 01/06/22

*Survey held at Mirage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP III

MV:

PV:

Nett:

4651

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

Report Format: _____

5. _____

MotorMed Pte Ltd

8 Kaki Bukit Ave 4 #02-14/44

Premier @ Kaki Bukit

Singapore 415875

Phone Number: 69777077

Fax Number: 69777080

Customer:			Date:		30/5/2022 12:40 PM	
Company: MIRAGE			VIN		SMD5744D	
License NO:			Technician:			
Odometer:			Order NO:			
VEHICLE ALIGNMENT REPORT BMW, 2 SERIES (F46) Standard Suspension, 16-19 (Customized)						
Primary Angles			Initial	Specifications Min. Max.		Final
Front	Caster	Left	----	----	----	----
		Right	----	----	----	----
	Camber	Left	-0°48'	-1°05'	-0°15'	-0°48'
		Right	-0°42'	-1°05'	-0°15'	-0°42'
	Toe	Left	0°05'	0°04'	0°08'	0°05'
		Right	-0°59'	0°04'	0°08'	-0°59'
Total		-0°54'	0°08'	0°16'	-0°54'	
Rear	Camber	Left	-1°42'	-1°50'	-1°40'	-1°42'
		Right	-1°30'	-1°50'	-1°40'	-1°30'
	Toe	Left	-0°01'	0°07'	0°11'	-0°01'
		Right	0°05'	0°07'	0°11'	0°05'
		Total	0°05'	0°14'	0°22'	0°05'
	Thrust Angle		0°03'	0°12'		0°03'
Secondary Angles			Initial	Specifications Min. Max.		Final
SAI	Left	----	----	----	----	
	Right	----	----	----	----	
Included Angle	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Out On Turns	Left	----	1°12'	2°12'	----	
	Right	----	1°12'	2°12'	----	
Max Turn Inside	Left	----	38°36'	38°36'	----	
	Right	----	38°36'	38°36'	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	0.0"	----	----	0.0"	
	Rear	-0.3"	----	----	-0.3"	
Track Width Diff.		0.4"			0.4"	
Wheel Base Diff.		0.4"			0.4"	
Front Ride Height	Left	----	24.5"	25.3"	----	
	Right	----	24.5"	25.3"	----	
Rear Ride Height	Left	----	23.9"	24.7"	----	
	Right	----	23.9"	24.7"	----	
Frame Angle						----