



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005176/Kqy3e2 Date: 24/06/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 5084R	Veh. Inspected	GBL 6006H	
Policy No.	D21MTPVE002373	Coverage (\$)	0.00	
Claim No.	CMTD2201830/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	31/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VSKYBAM20Z0172543	Colour	GREY	
Odometer	113608 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	YOKOHAMA	2 mm	
L/H Front Tyre	185/70 R14	YOKOHAMA	2 mm	
R/H Rear Tyre	185/70 R14	YOKOHAMA	8 mm	
L/H Rear Tyre	185/70 R14	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2022	Inspection Date	07/06/2022	
Survey held at	BLK 5035 AMK IND PK 2 #01-345			
Repairer	TRUST AUTOWORKS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	