

08/11/22 wef
ASS. REC. BY: *Tom*

REF:

CS/HLA 22005188/Rqy³

5452

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SKJ 574ST*

at Workshop m/s *GUAN ANNU SVL*

of *7, SIN MINH Ind EST #01-82*

Insured: *HLA*

Policy No.

Claim No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

22K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKJ 574ST

Yr Regn: *2013 / APR*

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: *VOLKSWAGEN PASSAT 1.4TSI* c.c. *1390*

Colour: *BLACK* A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: *148536* T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No:

C/No: *NVW2223CZ0P029577*

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: *225/40ZR18*

R: *225/40ZR18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *11/05/22*

D.O.I. *02/08/22*

Survey held at

GUAN ANNU

Des. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

N/S Fnt & O/S Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

REPAIR LIMIT - 4K

ESTIMATING RANGE OF REPAIR / no. of days - (1K-2K) / 3 days

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	5451
Vehicle No.:	SKJ5745T
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Aug 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT 1.4 TSI DSG 3623A7
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	CAXB99526
Chassis No.:	WVWZZZ3CZDP029577
Maximum Power Output:	90.0kW (120 bhp)
Open Market Value:	\$27,835.00
Original Registration Date:	18 Apr 2013
First Registration Date:	18 Apr 2013
Transfer Count:	0
Actual ARF Paid:	\$25,969.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2023
PARF Rebate Amount:	\$12,984.00
COE Expiry Date:	17 Apr 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$61,029.00
COE Rebate Amount:	\$4,305.00
Total Rebate Amount:	\$17,289.00

The information contained herein is correct as at 03 Aug 2022

OK

Volkswagen Passat 1.4A TSI

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$43,800****Depreciation** ⓘ

\$16,810 /yr

[View models with similar depre](#)**Reg Date**

18-Jul-2014

(1yr 11mths 14days COE left)

Mileage

16,500 km (2k /yr)

Manufactured ⓘ

2013

Road Tax ⓘ

\$620 /yr

Transmission

Auto

Dereg Value ⓘ\$24,132 as of today ([change](#))**OMV** ⓘ

\$24,877

COE ⓘ

\$61,990

ARF ⓘ

\$21,828

Engine Cap

1,390 cc

Power

90.0 kW (120 bhp)

Curb Weight ⓘ

1,463 kg

No. of Owners ⓘ

1

Type of Vehicle

Luxury Sedan