

Immediate Advice

To: AXA Insurance Pte Ltd 15/6/2022

Survey Details:

Date of loss	30-May-22
Date of appointment	1-Jun-22
Date of survey	13-Jun-22
Location of survey	EM SOLUTION PTE LTD

Vehicle Details:

Claim Type:	Third Party	y Claim	
Vehicle number	SMA 3695	SMA 3695R	
Make and Model	HONDA SH	HONDA SHUTTLE 1.5G CVT	
Date of registration	4/4/2018	4/4/2018	
Excess	-		
Market Value	\$	77,000.00	
Parf Rebate	\$	29,973.00	
Nett Loss	\$	47,027.00	

Repair details:

Initial Estimate	\$	4,993.96
IIIIliai LStiiiiate	Ą	4,333.30

Proposed/Revised repair cost:

Lump Sum(if applicable)	
Total	\$ 4,370.84
Labour	\$ 750.00
Check items (estimate)	\$ 1,777.04
Parts	\$ 1,843.80

Number of days for repair	<u>5</u>



51 UBI AVE 1, #91-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Damages consistent		

Mandate:

Liability(TP)	%]
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	