

ASS. REC. BY:

REF:

GAZ/ 22 003210/kc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKR 69337

Yr Regn:

02, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru

Forester

C.C.

1995

Colour

M. Grey

A/C:

Insured / Std / Nil / NA

Sp. Reading

132048

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

SFISKE 5E 604108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI /
TOYO / YOKO or

Goform

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/5/22

D.O.I.

23/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ 11/9 81003.00 Co-hr (Red. 2158.45, 68%)

Date/Time, File Pass to?

☐

Prell. Report

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

TP

Lump Sum / (B.I) (\$

1003.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 254G

Vehicle Details

Vehicle No.: SKR6933T
Vehicle to be Exported: Yes
Intended Deregistration Date: 20 May 2022
Vehicle Make: SUBARU
Vehicle Model: FORESTER 2.0I-L CVT ABS D/AIRBAG AWD S/R
Primary Colour: Grey
Manufacturing Year: 2014
Engine No.: FB201561333
Chassis No.: JF1SJ5KC5EG041078
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$14,969.00
Original Registration Date: 28 Feb 2015
First Registration Date: 28 Feb 2015
Transfer Count: 0
Actual ARF Paid: \$14,969.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Feb 2025
PARF Rebate Amount: \$8,981.00

Intended COE Rebate Details

COE Expiry Date: 27 Feb 2025
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$70,890.00
COE Rebate Amount: \$19,642.00
Total Rebate Amount: \$28,623.00

The information contained herein is correct as at 20 May 2022

OK

TJD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/05/2022 20:33 (SGT)
Date of Accident 20/05/2022 12:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information OPEN CARPARK @WHAMPOA FOOD CTR
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKR6933T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner QUEK KAI LOO
NRIC No SXXXX254G
Email Address kailooq@gmail.com
Mobile Phone No (Phone) +65-96779776
Alternative Phone No +65-96779776

VEHICLE PARTICULARS

Manufacturer Subaru
Model FORESTER 2.0I-L CVT ABS D/AIRBAG AWD S/R
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1995

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5120969301-01
Cover Note Number 28/02/2022 -27/02/2023

DRIVER

Name of Driver QUEK KAI LOO
NRIC No SXXXX254G

Date Of Birth	26/08/1959
Occupation	Indoor
Date Of Driving Pass	25/08/1984
Driving experience	37 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96779776
Alt. Phone Number	+65-96779776
Email Address	kailooq@gmail.com
Address	BLK 213 BISHAN ST 23 #06-243
Address complement	-
Postcode	570213
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER SKETCH ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3754H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

open c / park
@ Whampoa Food CN

A = SKR6933T
B = YP3754H

A = SKR6933T
B = YP3754H

Doa: 20/5/22 Time: 1230hrs Ins: NTHC

After lunch, I came back to my vehicle - I then realized that m/lorry (B) was touching onto my parked vehicle - I waited for the driver to come back about 10mins later to show him that his lorry had collided onto my vehicle frontal.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2

MT/1173220-001

SKETCH PLAN

IMPORTANT NOTICE

1. VEHICLE NO.: SKR 6933T

2. INSURER CO.: NTM C

3. ACCIDENT DATE & TIME: 20/5/22

1230hrs

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



E
ATION
Chamber





Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKR 6933T
TP/GA

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037

FAX: 62353354

ATTN: Motor Claim Department

WS Ref: TP GA

Claim Type: Third Party

Accident Date: 20/05/2022

Claim No: ES2290857

Estimate No: ES2290857/YISHUN

Date: 23 Aug 2022

Policy No:

Veh Reg No: SKR6933T

Make/Model: SUBARU SUBARU
FORESTER 2.0i

Chassis No: JF1SJ5KC5EG041078

Engine No:

Reg. Date: 28/02/2015

NOT Withheld

\$1003.00

Recovery After Paint

3 days

Estimate Repair Cost to Vehicle No : SKR6933T

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	320.00	1 PC	320.00	✓
2 FRONT BUMPER REINFORCEMENT	205.00	1 PC	205.00	✗
3 FRONT BUMPER REINFORCEMENT OUTER PANEL	98.00	1 PC	98.00	✗
4 HEADLAMP RH	1,200.00	1 PC	1,200.00	✗
			1,823.00	
	Add 15%		273.45	2,096.45
Special Net				
5 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
				35.00
Labour				
6 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, GRILLE, TO KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME	480.00	1 LA	480.00	250
7 PUTTY & RESPRAY ON FRT BUMPER, GRILLE, REINFORCEMENT	550.00	1 LA	550.00	350
				1,030.00
			Total	S\$ 3,161.45
			Add GST @ 7%	221.30
			Total Amount payable	S\$ 3,382.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE