(08/11/13) wef

ASS. REC. BY: Rasu

REF: CS/CTI 22005216/Rpy 3

63K

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGF 53H

at Workshop m/s Volkswagen

of 247, Alexandra Rd

Insured: CTI

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 108K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGF 53H Yr Regn: 2019 / JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: SKODA SUPERB AMBITION 2.0A c.c 1984

Colour RED A/C: Insured / Std / NI / NA

Sp.Reading 93648 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: TMBBD8NPX3761085Y

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18

R: --

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 29/05/22 D.O.I. 03/06/22

Survey held at Volkswagen

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 63K
	05/07/22 P/P $22,629.27 /- with 13 days of repair
	(Red, $9454.64,29%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 05/07/22 ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 13

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

__S + RS, __SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($ 22,629.27)