

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/3

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
NADARAJOO
S/O SUPPIAH
604 YISHUN STREET 61
#07-327
Singapore 760604

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

31-05-2022
5211001170
200208384E
30001
2022015716/ 1
31-05-2022
Dass Anthonidas
Christopher

License plate SGF53H	Model code 3V33SC	First registration 30-01-2019	VIN TMBBD8NPXJ7610854	Model SUPERB Gr1AMB TS162/2.0A6F	Mileage 20
-------------------------	----------------------	----------------------------------	--------------------------	-------------------------------------	---------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
3V5807421	Cover For REAR BUMPER	1	pcs.	2,124.92	#1	2,124.92	2,273.66
3V5807441	Cover For TOWING CAP	1	pcs.	31.57	#1	31.57	33.78
3V5807393	Guide Piec LHR BUMPER BRACKET (SIDE)	1	pcs.	58.52	#1	58.52	62.62
3V5807394	Guide Piec RHR BUMPER BRACKET (SIDE)	1	pcs.	58.52	#1	58.52	62.62
3V5807393A	Guide Piec LHR BUMPER BRACKET (UPPER)	1	pcs.	58.52	#1	58.52	62.62
3V5807394A	Guide Piec RHR BUMPER BRACKET (UPPER)	1	pcs.	58.52	#1	58.52	62.62
3V5807863	Retaining RR BUMPER BRACKET (CTR)	1	pcs.	95.52	#1	95.52	102.21
3V5919486A	Sensor Bracket	1	pcs.	45.94	#1	45.94	49.16
3V5919485	Sensor Bracket	1	pcs.	45.94	#1	45.94	49.16
3V5919486	Sensor Bracket	1	pcs.	45.94	#1	45.94	49.16
3V5919485A	Sensor Bracket	1	pcs.	45.94	#1	45.94	49.16
5Q0919133 9B9	Seal Ring Satin Black	1	pcs.	1.46	#1	5.84	6.25
5Q0919275C GRU	Sensor Primed	1	pcs.	190.18	#1	760.72	813.97
3V5971104C	Harness Fo REAR PARKING SENSOR WIRE HOUSING	1	pcs.	81.55	#1	81.55	87.26
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	#1	85.94	91.96
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	#1	68.85	73.67
3V5807305B	Unbekannt REINFORCEMENT	1	pcs.	674.24	#1	674.24	721.44
3V5807521 9B9	Spoiler RR BUMPER LOWER SPOILER	1	pcs.	339.02	#1	339.02	362.75
3V5945105	Reflector LH	1	pcs.	48.26	#1	48.26	51.64
3V5945106	Reflector RH	1	pcs.	48.26	#1	48.26	51.64
3V5945207A	Taillight LHR OUTER	1	pcs.	881.46	#1	881.46	943.16
3V5945307B	Led Tail L LHR INNER	1	pcs.	594.24	#1	594.24	635.84
3V5945208A	Taillight RHR OUTER	1	pcs.	881.46	#1	881.46	943.16
3V5945308C	Led Tail L RHR INNER	1	pcs.	594.24	#1	594.24	635.84
3V5827023D	Rear Trunk	1	pcs.	4,644.37	#1	4,644.37	4,969.48
3V0827505C	Hood Lock	1	pcs.	173.67	#1	173.67	185.83

ŠKODA Centre Singapore

26 Leng Kee Rd
 Singapore 159104
 Biz. Reg. No.: 199101494Z
 GST No.: M200985052



Quotation

Non binding - Preview

Page 3/3

Company
 CHINA TAIPING INSURANCE (S) PL
 3 ANSON ROAD
 #18-00 SPRINGLEAF TOWER
 Singapore 079909

Customer Details:
 Mr
 NADARAJOO
 S/O SUPPIAH
 604 YISHUN STREET 61
 #07-327
 Singapore 760604

Document no.
 Document date 31-05-2022
 Customer no. 5211001170
 Customer GST-ID 200208384E
 Dealer 30001
 Job order number 2022015716/ 1
 Job order date 31-05-2022
 Service Advisor Dass Anthonidas
 Christopher

License plate SGF53H	Model code 3V33SC	First registration 30-01-2019	VIN TMBBD8NPXJ7610854	Model SUPERB Gr1AMB TS162/2.0A6F	Mileage 20
-------------------------	----------------------	----------------------------------	--------------------------	-------------------------------------	---------------

Quotation valid till 07-06-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	27,862.45	7%	2,003.57	28,622.45	30,626.02
Total	760.00	27,862.45		2,003.57	28,622.45	30,626.02

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Paul
 Hp 90010068
 10 days + 3 = 13 days
 P/P
 03/06/22 @ 1015
 Resurvey before paint