

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |   |  |                       |  |  |
|---|---|---|--|-----------------------|--|--|
|   | UNITED OVERSEAS INSURANCE LTD   |   | Ref:   | CS/UOI22005221/Kty3e2 |  |  |
|   | 146 ROBINSON ROAD<br>#02-01 UOI BUILDINGSINGAPORE 068909  |   | Date:  | 14/06/2022            |  |  |
|   |   |   | Code:  | UOI2                  |  |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |   |  |                       |  |  |
|   | Insured Veh.  | YP 3128R  | Veh. Inspected                                     | SMN 5392H             |  |  |
|   | Policy No.  |   | Coverage (\$)                                      | 0.00                  |  |  |
|   | Claim No.   | M11D15402206  | Excess (\$)  | 0.00                  |  |  |
|   | Assign From   | JOSEPHINE WONG  | Assign Date  | 01/06/2022            |  |  |
| 2. Vehicle Particulars & Condition                                |   |   |  |                       |  |  |
|   | Make & Model  | HONDA JAZZ (A)  | c.c  | 1498                  |  |  |
|   | Engine No.  | HIDDEN  | Year of Reg.                                       | 2015                  |  |  |
|   | Chassis No.   | JHMGK5850FX203571   | Colour   | METALLIC PEARL WHITE  |  |  |
|   | Odometer  | 167083 KM   | Steering   | IN ORDER              |  |  |
|   | Brakes  | IN ORDER  | Modification                                       | STANDARD ALLOY RIM    |  |  |
|   | General   | GOOD  |  |                       |  |  |
| 3. Conditions of Tyres  |   |   |  |                       |  |  |
|   |   | Size  | Make   | Balance               |  |  |
|   | R/H Front Tyre  | 185/55 R16  | WINDFORCE  | 8 mm                  |  |  |
|   | L/H Front Tyre  | 185/55 R16  | WINDFORCE  | 8 mm                  |  |  |
|   | R/H Rear Tyre   | 185/55 R16  | TOYO   | 7 mm                  |  |  |
|   | L/H Rear Tyre   | 185/55 R16  | TOYO   | 7 mm                  |  |  |
| 4.  | Description of Damages  |   |  |                       |  |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |   |  |                       |  |  |
|   | DAMAGES SEE DETAILS.  |   |  |                       |  |  |
| 5.  | General Information   |   |  |                       |  |  |
|   | Accident Date   | 31/05/2022  | Inspection Date                                    | 01/06/2022            |  |  |
|   | Survey held at WEI LEE MOTOR WORKS  |   |  |                       |  |  |
|   |   | BLOCK 9 SIN MING INDUSTRIAL ESTATE<br>#01-32<br>SINGAPORE 575644. |  |                       |  |  |
| 5a.   | Remarks   |   |  |                       |  |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |  |                       |  |  |
| 5b.   | Estimate Days of Repair   |   |  |                       |  |  |
|   |   |   | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days |                       |  |  |