

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |   |                |       |                     |  |
|---|---|---|----------------|-------|---------------------|--|
|   | UNITED OVERSEA  | AS INSURANCE LTD  |                | Ref:  | CS/UOI22005221/Kty3 |  |
|   | 146 ROBINSON RO<br>#02-01 UOI BUILD   | OAD<br>INGSINGAPORE 068909  |                | Date: | 01/06/2022          |  |
|   |   |   |                | Code: | UOI2                |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |   |                |       |                     |  |
|   | Insured Veh.  | YP 3128R  | Veh. Inspected | l     | SMN 5392H           |  |
|   | Policy No.  |   | Coverage (\$)  |       | 0.00                |  |
|   | Claim No.   |   | Excess (\$)    |       | 0.00                |  |
|   | Assign From   | JOSEPHINE WONG  | Assign Date    |       | 01/06/2022          |  |
| 2. Vehicle Particulars & Condition                                |   |   |                |       |                     |  |
|   | Make & Model  |   | c.c            |       | 0                   |  |
|   | Engine No.  | HIDDEN  | Year of Reg.   |       |                     |  |
|   | Chassis No.   |   | Colour         |       |                     |  |
|   | Odometer  | Steering  |                |       |                     |  |
|   | Brakes  |   | Modification   |       |                     |  |
|   | General   |   |                |       |                     |  |
| 3. Conditions of Tyres  |   |   |                |       |                     |  |
|   |   | Size  | Make           |       | Balance             |  |
|   | R/H Front Tyre  |   |                |       | mm                  |  |
|   | L/H Front Tyre  |   |                |       | mm                  |  |
|   | R/H Rear Tyre   |   |                |       | mm                  |  |
|   | L/H Rear Tyre   |   |                |       | mm                  |  |
| 4.  | Description of Damages  |   |                |       |                     |  |
|   |   |   |                |       |                     |  |
| 5.  |   |   |                |       |                     |  |
|   | Accident Date   | 31/05/2022  | Inspection Dat | е     | 01/06/2022          |  |
|   | Survey held at  | at WEI LEE MOTOR WORKS  |                |       |                     |  |
|   |   | BLOCK 9 SIN MING INDUSTRIAL ESTATE<br>#01-32<br>SINGAPORE 575644. |                |       |                     |  |
| 5a. Remarks   |   |   |                |       |                     |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                |       |                     |  |