

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1001803973

Claims No. 274632

Sum Insured: Excess: 1500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBG4479K Yr Regn: 2/8/17

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Fiat Fiorino c.c. 1748

Colour: White A/C: Insured / Std / Nil / NA

Sp. Reading: 10754 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: 2F422500006F36669

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / Std / STD A/Rim or

Tyre Size: F: 185/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: Falken

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 13/5/22 D.O.I. 2/6/22

Survey held at: Sim Lee Construction

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK-38K

Remark - The car able to start, the brake was function and the all tyre tread is not worn off.

8/7/22 Final fig \$4075 (red 0)

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Date/Time, File Return to?

2) 12/8/22-typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: MERIMEN

Lump Sum / L.B.E. (\$) \$4075.00

Sim Lee Construction & Transport Pte. Ltd.

7 Soon Lee Street #05-08 Ispace Singapore 627608

Tel: 6397 4285 Fax: 6397 4287 Email: simleeconstruction@gmail.com

97334227 Lugi Reg. No.: 198404289G

Samwoh Premix Pte Ltd
25E Sungei Kadut St 1
Singapore 729333

Stew (LKK)

2/6/22, 11.00am

8392 8813

00-NM AL

EXL - ?

4/5 P/P

M Bel my

5 days

24 May 2022

Dear Sir/Mdm,

Quotation for repair works

For Vehicle No. GBG4429K

Sim Lee Construction & Transport Pte. Ltd. is pleased to provide the following service:

1 x bonnet / DD	\$450.00
1 x head lamp (RH) / BR	\$360.00
1 x grille (top) / BR	\$190.00
1 x bumper (lower) / BR	\$650.00
1 x bumper (top) / BR	\$425.00
Svc charge for repair of front bonnet	\$200.00 /
Spray paint of bonnet by front panel	\$380.00 /
Sub-Total (Page 1 out of 1)	
	\$2,655.00
Grand Total (Excluding GST)	
	\$2,655.00

Payment terms : 30 days after invoicing.

Please send us a copy of your acknowledgement for us to start work.

Best regards,

Sim Lee Construction & Transport Pte. Ltd.

Acknowledgement

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name, position, company stamp